

SS-EN 1611-1 Wood Sorting System Report

Generated at: 2025-09-28_06-36-04

Session Summary

Total Pieces Processed: 7

Grade Perfect (No Defects): 0

Grade G2-0/G2-1 (Good Quality): 0

Grade G2-2/G2-3 (Fair Quality): 3

Grade G2-4 (Poor Quality): 4

Individual Piece Log

Piece #1: Grade G2-4

- Defect: Unsound Knot, Count: 3, Sizes (mm): 37.6, 29.5, 50.9

Piece #2: Grade G2-3

- Defect: Unsound Knot, Count: 3, Sizes (mm): 37.8, 29.6, 50.0

Piece #3: Grade G2-4

- Defect: Unsound Knot, Count: 3, Sizes (mm): 37.1, 29.5, 51.6

Piece #4: Grade G2-3

- Defect: Unsound Knot, Count: 1, Sizes (mm): 37.0

Piece #5: Grade G2-4

- Defect: Unsound Knot, Count: 4, Sizes (mm): 37.3, 29.8, 51.8, 33.0

Piece #6: Grade G2-4

- Defect: Unsound Knot, Count: 4, Sizes (mm): 37.2, 28.9, 53.2, 45.6

Piece #7: Grade G2-3

- Defect: Unsound Knot, Count: 3, Sizes (mm): 30.3, 43.4, 28.2