

SS-EN 1611-1 Wood Sorting System Report

Generated at: 2025-10-17_03-10-11

Session Summary

Total Pieces Processed: 59

Grade G2-0: 24

Grade G2-1: 5

Grade G2-2: 9

Grade G2-3: 21

Grade G2-4: 0

Individual Piece Log

Piece #59: Grade G2-3

- Defect: Crack Knot, Count: 2, Sizes (mm): 34.3, 43.9
- Defect: Missing Knot, Count: 3, Sizes (mm): 23.5, 4.1, 12.9