

SS-EN 1611-1 Wood Sorting System Report

Generated at: 2025-10-15_03-53-46

Session Summary

Total Pieces Processed: 89

Grade G2-0: 3

Grade G2-1: 5

Grade G2-2: 34

Grade G2-3: 46

Grade G2-4: 1

Individual Piece Log

Piece #87: Grade G2-3

- Defect: Missing Knot, Count: 1, Sizes (mm): 24.9
- Defect: Crack Knot, Count: 2, Sizes (mm): 30.9, 24.2
- Defect: Dead Knot, Count: 1, Sizes (mm): 21.1

Piece #88: Grade G2-3

- Defect: Missing Knot, Count: 3, Sizes (mm): 15.7, 17.0, 32.4
- Defect: Crack Knot, Count: 1, Sizes (mm): 43.3

Piece #89: Grade G2-3

- Defect: Dead Knot, Count: 3, Sizes (mm): 6.8, 7.9, 7.2
- Defect: Missing Knot, Count: 3, Sizes (mm): 14.1, 26.0, 25.1