

SS-EN 1611-1 Wood Sorting System Report

Generated at: 2025-10-15_04-11-52

Session Summary

Total Pieces Processed: 106

Grade G2-0: 3

Grade G2-1: 6

Grade G2-2: 34

Grade G2-3: 62

Grade G2-4: 1

Individual Piece Log

Piece #97: Grade G2-3

- Defect: Missing Knot, Count: 3, Sizes (mm): 33.2, 7.4, 48.2

Piece #98: Grade G2-3

- Defect: Missing Knot, Count: 2, Sizes (mm): 41.9, 44.9

Piece #99: Grade G2-3

- Defect: Missing Knot, Count: 2, Sizes (mm): 41.9, 37.4

Piece #100: Grade G2-3

- Defect: Missing Knot, Count: 2, Sizes (mm): 42.0, 46.6

Piece #101: Grade G2-3

- Defect: Missing Knot, Count: 4, Sizes (mm): 40.4, 44.7, 10.3, 29.5

Piece #102: Grade G2-3

- Defect: Missing Knot, Count: 2, Sizes (mm): 31.1, 21.1

Piece #103: Grade G2-3

- Defect: Missing Knot, Count: 3, Sizes (mm): 23.9, 18.8, 37.1

Piece #104: Grade G2-3

- Defect: Crack Knot, Count: 1, Sizes (mm): 51.6

- Defect: Missing Knot, Count: 2, Sizes (mm): 31.9, 38.8

Piece #105: Grade G2-3

- Defect: Crack Knot, Count: 2, Sizes (mm): 30.5, 39.3

- Defect: Missing Knot, Count: 3, Sizes (mm): 26.1, 4.4, 20.6

Piece #106: Grade G2-3

- Defect: Missing Knot, Count: 4, Sizes (mm): 26.5, 2.7, 29.2, 11.6

- Defect: Crack Knot, Count: 1, Sizes (mm): 38.2