

SS-EN 1611-1 Wood Sorting System Report

Generated at: 2025-10-24_16-12-12

Session Summary

Total Pieces Processed: 13

Grade G2-0: 0

Grade G2-1: 0

Grade G2-2: 2

Grade G2-3: 11

Grade G2-4: 0

Individual Piece Log

Piece #6: Grade G2-3

- Defect: Missing Knot, Count: 4, Sizes (mm): 14.7, 10.0, 10.1, 35.6

Piece #7: Grade G2-3

- Defect: Missing Knot, Count: 4, Sizes (mm): 14.4, 15.7, 15.3, 12.2

- Defect: Dead Knot, Count: 1, Sizes (mm): 39.4

Piece #8: Grade G2-3

- Defect: Missing Knot, Count: 2, Sizes (mm): 36.5, 11.0

Piece #9: Grade G2-3

- Defect: Missing Knot, Count: 4, Sizes (mm): 16.7, 11.5, 35.2, 10.9

Piece #10: Grade G2-3

- Defect: Dead Knot, Count: 2, Sizes (mm): 19.5, 15.9

- Defect: Crack Knot, Count: 1, Sizes (mm): 30.4

- Defect: Missing Knot, Count: 3, Sizes (mm): 7.3, 22.9, 16.0

Piece #11: Grade G2-3

- Defect: Dead Knot, Count: 2, Sizes (mm): 19.9, 21.9

- Defect: Crack Knot, Count: 1, Sizes (mm): 33.8

- Defect: Missing Knot, Count: 1, Sizes (mm): 17.2

Piece #12: Grade G2-3

- Defect: Missing Knot, Count: 4, Sizes (mm): 26.2, 13.8, 7.2, 38.3

- Defect: Dead Knot, Count: 1, Sizes (mm): 23.0

Piece #13: Grade G2-3

- Defect: Missing Knot, Count: 5, Sizes (mm): 26.7, 10.2, 6.9, 20.2, 32.0

- Defect: Dead Knot, Count: 1, Sizes (mm): 22.5