

SS-EN 1611-1 Wood Sorting System Report

Generated at: 2025-10-24_16-21-23

Session Summary

Total Pieces Processed: 23

Grade G2-0: 0

Grade G2-1: 0

Grade G2-2: 2

Grade G2-3: 21

Grade G2-4: 0

Individual Piece Log

Piece #18: Grade G2-3

- Defect: Missing Knot, Count: 2, Sizes (mm): 29.9, 33.5
- Defect: Dead Knot, Count: 4, Sizes (mm): 9.5, 22.2, 10.9, 8.1
- Defect: Crack Knot, Count: 1, Sizes (mm): 17.5

Piece #19: Grade G2-3

- Defect: Dead Knot, Count: 2, Sizes (mm): 31.9, 36.5
- Defect: Missing Knot, Count: 1, Sizes (mm): 26.3

Piece #20: Grade G2-3

- Defect: Missing Knot, Count: 2, Sizes (mm): 40.0, 34.2
- Defect: Dead Knot, Count: 1, Sizes (mm): 20.9

Piece #21: Grade G2-3

- Defect: Dead Knot, Count: 5, Sizes (mm): 35.8, 16.7, 32.5, 18.2, 36.8
- Defect: Missing Knot, Count: 1, Sizes (mm): 29.2

Piece #22: Grade G2-3

- Defect: Missing Knot, Count: 2, Sizes (mm): 31.9, 35.3

Piece #23: Grade G2-3

- Defect: Dead Knot, Count: 3, Sizes (mm): 24.1, 30.6, 39.2
- Defect: Missing Knot, Count: 2, Sizes (mm): 21.4, 44.8