

|                  |            |               |                          |
|------------------|------------|---------------|--------------------------|
| Lot 7/Tract 0001 | Defects: 4 | CH Defects: 2 | Checklist Inspections: 5 |
|------------------|------------|---------------|--------------------------|

|                      |  |  |  |
|----------------------|--|--|--|
| <div></div> Ferguson |  |  |  |
|----------------------|--|--|--|

|                      |                            |                   |                                |
|----------------------|----------------------------|-------------------|--------------------------------|
| Code: ZZ_026         | Location: Kitchen          | Description: Test | <div>CRITICAL</div> Incomplete |
| Category: Appliances | Type: Appliance(s) missing |                   |                                |
| Partner: Ferguson    |                            |                   |                                |

|                      |                   |                   |            |
|----------------------|-------------------|-------------------|------------|
| Code: ZZ_027         | Location: Kitchen | Description: Test | Incomplete |
| Category: Appliances | Type: Scratch(es) |                   |            |
| Partner: Ferguson    |                   |                   |            |

|                          |  |  |  |
|--------------------------|--|--|--|
| <div></div> G&G Concrete |  |  |  |
|--------------------------|--|--|--|

|                       |                    |                   |                                |
|-----------------------|--------------------|-------------------|--------------------------------|
| Code: ZZ_024          | Location: Backyard | Description: Test | <div>CRITICAL</div> Incomplete |
| Category: Concrete    | Type: Crack        |                   |                                |
| Partner: G&G Concrete |                    |                   |                                |

|                       |                         |                     |            |
|-----------------------|-------------------------|---------------------|------------|
| Code: ZZ_025          | Location: Backyard      | Description: Test 2 | Incomplete |
| Category: Concrete    | Type: Concrete hump/dip |                     |            |
| Partner: G&G Concrete |                         |                     |            |