


All Defects

Lot 35/Tract 6100

 Elia Painting

Code: ZZ_3763	Location: Exterior		
Category: Paint	Type: Cleanup	Description: Paint stucco pop outs Dovetail color	Incomplete
Partner: Elia Painting			

 Premier Door

Code: ZZ_3764	Location:	Description: Bath 2 door handle is scratched Laundry room door handle scratched Pantry door handle scratched Master bathroom handle scratched	
Category: Millwork	Type:		Incomplete
Partner: Premier Door			