

All Defects		Lot 28/Tract 6100		
<div><div></div><div>Cabinet Connection</div></div>				
Code: ZZ_3855		Location:	Description: Adjust drawer in kitchen left of sink	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
<div><div></div><div>Central Valley Rain Gutters</div></div>				
Code: ZZ_3868		Location:	Description: Missing gutter downspout in backyard	Incomplete
Category: Rain Gutters		Type:		
Partner: Central Valley Rain Gutters				
<div><div></div><div>Elia Painting</div></div>				
Code: ZZ_3851		Location:	Description: Paint touch up bath h 2 door	Incomplete
Category: Paint		Type:		
Partner: Elia Painting				
Code: ZZ_3852		Location:	Description: Paint touch up on window sill in bed 3	Incomplete
Category: Paint		Type:		
Partner: Elia Painting				
Code: ZZ_3853		Location:	Description: Caulk trim around closet in bed 3	Incomplete
Category: Paint		Type:		
Partner: Elia Painting				
Code: ZZ_3854		Location:	Description: Paint touch up throughout home	Incomplete
Category: Paint		Type:		
Partner: Elia Painting				
Code: ZZ_3856		Location:	Description: Paint touch up in bed 3 walls	Incomplete
Category: Paint		Type:		
Partner: Elia Painting				

Code: ZZ_3857	Location:		
Category: Paint	Type:	Description: Bed 3 closet doors	Incomplete
Partner: Elia Painting			
Code: ZZ_3858	Location:		
Category: Paint	Type:	Description: Paint touch up in bed 2 walls	Incomplete
Partner: Elia Painting			
Code: ZZ_3859	Location:		
Category: Paint	Type:	Description: Paint touch up closet doors in bed 2	Incomplete
Partner: Elia Painting			
Code: ZZ_3860	Location:		
Category: Paint	Type:	Description: Paint touch up in hall	Incomplete
Partner: Elia Painting			
Code: ZZ_3862	Location:		
Category: Paint	Type:	Description: Paint touch up in great room	Incomplete
Partner: Elia Painting			
Code: ZZ_3863	Location:		
Category: Paint	Type:	Description: Paint touch up in hall	Incomplete
Partner: Elia Painting			
Code: ZZ_3864	Location:		
Category: Paint	Type:	Description: Paint touch up on walls in great room	Incomplete
Partner: Elia Painting			
Code: ZZ_3866	Location:		
Category: Paint	Type:	Description: Paint touch up in master closet attic access	Incomplete
Partner: Elia Painting			
Code: ZZ_3869	Location:		
Category: Paint	Type:	Description: Paint corbels on front of home	Incomplete
Partner: Elia Painting			



Code: ZZ\_3849

Category: Fence

Partner: Fenceworks

Location:

Type:

Description: Fence missing

Incomplete



Code: ZZ\_3861

Category: Fire Sprinklers

Partner: HSI

Location:

Type:

Description: Fire sprinkler cap in hall missing

Incomplete



Code: ZZ\_3867

Category: Stucco

Partner: Tri Valley Plastering & Drywall

Location:

Type:

Description: Stucco crack and hole by front door

Incomplete



Code: ZZ\_3850

Category: Electrical

Partner: Westech

Location:

Type:

Description: Missing globe in bath 2 vanity light

Incomplete

Code: ZZ\_3865

Category: Electrical

Partner: Westech

Location:

Type:

Description: Missing vanity light in master bath

Incomplete