

All Defects		Lot 53/Tract 6102		
<div><div></div>Cabinet Connection</div>				
Code: ZZ_092		Location:	Description: Scratches on face of master cabinets	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_094		Location:	Description: Various cabinet scratches in kitchen	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
<div><div></div>Everlast Paint</div>				
Code: ZZ_089		Location:	Description: Paint on stair rail	Incomplete
Category: Paint		Type:		
Partner: Everlast Paint				
Code: ZZ_090		Location:	Description: Various paint touch up in bed 5	Incomplete
Category: Paint		Type:		
Partner: Everlast Paint				
Code: ZZ_091		Location:	Description: Various paint in bed 4	Incomplete
Category: Paint		Type:		
Partner: Everlast Paint				
<div><div></div>Quality Plumbing</div>				
Code: ZZ_093		Location:	Description: No hot water master bath tub	Incomplete
Category: Plumbing		Type:		
Partner: Quality Plumbing				