

Lot 5/Tract 6377	Items: 18	CH Items: 1	Checklist Inspections: 314
------------------	-----------	-------------	----------------------------------

<div><div></div>Anlin Windows</div>			
Code: ZZ_1770			
Category: Windows	Location: Dining Nook	Description: Scratches on slider	Incomplete
Partner: Anlin Windows	Type: Window glass has scratches		
<div><div></div>Cabinet Connection</div>			
Code: ZZ_1765			
Category: Cabinets	Location: Bathroom 1	Description: Nail holes showing on Twe	Incomplete
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets		
Code: ZZ_1767			
Category: Cabinets	Location: Kitchen	Description: Finish nails on Twe	Incomplete
Partner: Cabinet Connection	Type: Cabinet drawers and/or doors need to be adjusted		
Code: ZZ_1768			
Category: Cabinets	Location: Kitchen	Description: Adjust cabinet doors and drawers	Incomplete
Partner: Cabinet Connection	Type: Cabinet drawers and/or doors need to be adjusted		
Code: ZZ_1775			
Category: Cabinets	Location: Bathroom 2	Description: Finish nails on twe	Incomplete
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets		
Code: ZZ_1776			
Category: Cabinets	Location: Laundry Room	Description: Adjust doors in laundry room	Incomplete
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets		
<div><div></div>Elia Painting</div>			

Code: ZZ_1769			
Category: Paint	Location: Bedroom 1	Description: Paint on exterior of window	Incomplete
Partner: Elia Painting	Type: Touch-up required		
Code: ZZ_1774			
Category: Paint	Location: Bathroom 2	Description: Clean paint off tile	Incomplete
Partner: Elia Painting	Type: Touch-up required		
Code: ZZ_1777			
Category: Paint	Location: Bedroom 3	Description: Caulking in corner of baseboard in corner of room	Incomplete
Partner: Elia Painting	Type: Caulking touch-up required at baseboard, window frame, trim/door frame, or wall corners		
Code: ZZ_1778			
Category: Paint	Location: Bedroom 3	Description: Touch up corner of wall in room	Incomplete
Partner: Elia Painting	Type: Touch-up required		
Code: ZZ_1779			
Category: Paint	Location: Bedroom 4	Description: Caulking in corner of room	Incomplete
Partner: Elia Painting	Type: Caulking touch-up required at baseboard, window frame, trim/door frame, or wall corners		
Code: ZZ_1780			
Category: Paint	Location: Bedroom 4	Description: Touch up by baseboard	Incomplete
Partner: Elia Painting	Type: Touch-up required		
Code: ZZ_1781			
Category: Paint	Location: Stairwell	Description: Paint touch up on walls in stairwell	Incomplete
Partner: Elia Painting	Type: Touch-up required		
Code: ZZ_1782			
Category: Paint	Location: Bedroom 2	Description: Touch up in corners of baseboards in room.	Incomplete
Partner: Elia Painting	Type: Touch-up required		

Lot 5/Tract 6377		Items: 18	CH Items: 1	Checklist Inspections: 314
Code: ZZ_1771				
Category: Landscaping	Location: Exterior		Description: Grass not installed	CRITICAL Incomplete
Partner: Landscape Connection	Type: Missing			
<div><div></div>Ohanians Drywall</div>				
Code: ZZ_1766				
Category: Drywall	Location: Bathroom 1		Description: Drywall texture on bullnose	Incomplete
Partner: Ohanians Drywall	Type: Drywall texture issues			
<div><div></div>Tri Valley Plastering &amp; Drywall</div>				
Code: ZZ_1773				
Category: Stucco	Location: Exterior		Description: Stucco fog around exterior and fix cracks on back side	Incomplete
Partner: Tri Valley Plastering & Drywall	Type: Inconsistent Fog coat			
<div><div></div>True Frame</div>				
Code: ZZ_1772				
Category: Framing	Location: Exterior		Description: Hole in wood siding	Incomplete
Partner: True Frame	Type: Fascia, wood railing, siding, columns, or any other exterior wood product missing or damaged			