


All Defects		Lot 22/Tract 6164		
<div><div></div>Anlin Windows</div>				
Code: ZZ_1637		Location:	Description: Slide and glide on all windows and install screens	Incomplete
Category: Windows		Type:		
Partner: Anlin Windows				
<div><div></div>Cabinet Connection</div>				
Code: ZZ_1634		Location:	Description: Cabinet touch in kitchen	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_1635		Location:	Description: Backer of cabinet in upper cabinet in kitchen right of fridge	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_1636		Location:	Description: Nail holes on front of island	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_1639		Location:	Description: Replace face of appliance surround damaged	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_1655		Location:	Description: Cabinet scratches in bath 3 right vanity	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_1659		Location:	Description: Adjust right drawer in bath 3	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_1661		Location:	Description: Adjust drawer on left side in bath 2	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				

Code: ZZ_1667	Location:		
Category: Cabinets	Type:	Description: Scratch in master bath cabinets	Incomplete
Partner: Cabinet Connection			
<div><div></div>Donald P. Dick</div>			
Code: ZZ_1653	Location:		
Category: HVAC	Type:	Description: Install exhaust fan cover in bath 3	Incomplete
Partner: Donald P. Dick			
<div><div></div>Elia Painting</div>			
Code: ZZ_1643	Location:		
Category: Paint	Type:	Description: Paint base in great room	Incomplete
Partner: Elia Painting			
Code: ZZ_1644	Location:		
Category: Paint	Type:	Description: Paint by bullnose by kitchen	Incomplete
Partner: Elia Painting			
Code: ZZ_1645	Location:		
Category: Paint	Type:	Description: Paint and drywall in Harry Potter closet and caulk bottom of baseboard	Incomplete
Partner: Elia Painting			
Code: ZZ_1649	Location:		
Category: Paint	Type:	Description: Paint entry by powder bath	Incomplete
Partner: Elia Painting			
Code: ZZ_1651	Location:		
Category: Paint	Type:	Description: Paint in stairwell	Incomplete
Partner: Elia Painting			
Code: ZZ_1652	Location:		
Category: Paint	Type:	Description: Caulk baseboard in bed 5 and paint bottom of base	Incomplete
Partner: Elia Painting			

Code: ZZ_1654			
Category: Paint	Location:	Description: Remove paint of right vanity in bath 3	Incomplete
Partner: Elia Painting	Type:		
Code: ZZ_1656			
Category: Paint	Location:	Description: Caulk baseboard in bed 4 and correct transition line on bullnose	Incomplete
Partner: Elia Painting	Type:		
Code: ZZ_1658			
Category: Paint	Location:	Description: Paint baseboard in bed 3	Incomplete
Partner: Elia Painting	Type:		
Code: ZZ_1665			
Category: Paint	Location:	Description: Nail pop in master bed by outlet	Incomplete
Partner: Elia Painting	Type:		
<div></div> Ferguson			
Code: ZZ_1638			
Category: Appliances	Location:	Description: Install appliances	Incomplete
Partner: Ferguson	Type:		
Code: ZZ_1670			
Category: Appliances	Location:	Description: Fix hood in kitchen where buttons got pushed in	Incomplete
Partner: Ferguson	Type:		
<div></div> Fresno Shower Door & Mirror			
Code: ZZ_1666			
Category: Shower Door & Mirror	Location:	Description: Install shower enclosure in master bath	Incomplete
Partner: Fresno Shower Door & Mirror	Type:		
<div></div> G&G Concrete			

Code: ZZ_1674	Location:		
Category: Concrete	Type:	Description: Finish concrete sidewalk	Incomplete
Partner: G&G Concrete			



Code: ZZ_1640	Location:		
Category: Tile	Type:	Description: Install tile on side of cabinet by oven on toe kick	Incomplete
Partner: Ideal Custom Tile			

Code: ZZ_1641	Location:		
Category: Tile	Type:	Description: Replace one lifter tile in great room	Incomplete
Partner: Ideal Custom Tile			

Code: ZZ_1642	Location:		
Category: Tile	Type:	Description: Fill grout on edges in great room	Incomplete
Partner: Ideal Custom Tile			

Code: ZZ_1646	Location:		
Category: Tile	Type:	Description: Caulk baseboard by stairs	Incomplete
Partner: Ideal Custom Tile			

Code: ZZ_1647	Location:		
Category: Tile	Type:	Description: Fill grout in den remove pencil marks	Incomplete
Partner: Ideal Custom Tile			

Code: ZZ_1662	Location:		
Category: Tile	Type:	Description: Remove pencil marks on tile in bath 2	Incomplete
Partner: Ideal Custom Tile			

Code: ZZ_1669	Location:		
Category: Tile	Type:	Description: Remove pencil on tile in master bath water closet	Incomplete
Partner: Ideal Custom Tile			

Code: ZZ_1671	Location:		
Category: Tile	Type:	Description: Large gaps at tile in laundry room	Incomplete
Partner: Ideal Custom Tile			

LinkUs

Code: ZZ_1657	Location:		
Category: Low Voltage Electrical	Type:	Description: Finish data pre wire in bed 3	Incomplete
Partner: LinkUs			

Ohanians Drywall

Code: ZZ_1648	Location:		
Category: Drywall	Type:	Description: Drywall hole in den	Incomplete
Partner: Ohanians Drywall			

Premier Door

Code: ZZ_1664	Location:		
Category: Millwork	Type:	Description: Damaged trim on standing door to master bedroom	Incomplete
Partner: Premier Door			

Quality Plumbing

Code: ZZ_1650	Location:		
Category: Plumbing	Type:	Description: Missing toilet roll holder in powder bath	Incomplete
Partner: Quality Plumbing			

Code: ZZ_1660	Location:		
Category: Plumbing	Type:	Description: Missing toilet paper holder in bath 2	Incomplete
Partner: Quality Plumbing			

Code: ZZ_1668	Location:		
Category: Plumbing	Type:	Description: Caulk master bath tub	Incomplete
Partner: Quality Plumbing			

Simas Flooring & Design

Code: ZZ_1663	Location:		
Category: Carpet / Hardwood / Laminate	Type:	Description: Place carpet back in bed 2	Incomplete
Partner: Simas Flooring & Design			



Tri Valley Plastering & Drywall

Code: ZZ_1672			
Category: Stucco	Location:	Description: Stucco touch up around whole home	Incomplete
Partner: Tri Valley Plastering & Drywall	Type:		

Code: ZZ_1673			
Category: Stucco	Location:	Description: Touch up pop outs in front of home	Incomplete
Partner: Tri Valley Plastering & Drywall	Type:		