

All Defects

Lot 24/Tract 6100

Cabinet Connection

Code: ZZ_4135	Location:	Description: Cabinet scratches and nail holes in master bath on faces of doors and drawers	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
Code: ZZ_4136	Location:	Description: Cabinet scratches on cabinet lowers to the left of oven in kitchen	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
Code: ZZ_4137	Location:	Description: Adjust the kitchen crown left of oven is really visible	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
Code: ZZ_4138	Location:	Description: Cabinet scratches to the right of oven uppers and lowers	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
Code: ZZ_4139	Location:	Description: Adjust cabinet door faces above fridge surround	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
Code: ZZ_4140	Location:	Description: Cabinet scratch on drawer on kitchen island	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
Code: ZZ_4141	Location:	Description: Cabinet scratches on faces of doors in bath 2	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			