

All Defects		Lot 7/Tract 6100		
<div><div></div><div>Cabinet Connection</div></div>				
Code: ZZ_4142				
Category: Cabinets	Location:	Description: Cabinet scratches on upper door faces to the right of oven		Incomplete
Partner: Cabinet Connection	Type:			
Code: ZZ_4143				
Category: Cabinets	Location:	Description: Replace 2 door fronts and 2 drawer fronts on cabinet lowers to the right of oven		Incomplete
Partner: Cabinet Connection	Type:			
Code: ZZ_4144				
Category: Cabinets	Location:	Description: Cabinet scratches on door and drawer faces to the right of oven lowers		Incomplete
Partner: Cabinet Connection	Type:			
Code: ZZ_4145				
Category: Cabinets	Location:	Description: Cabinet scratches on lower cabinet left of oven on fronts of doors and drawers		Incomplete
Partner: Cabinet Connection	Type:			
Code: ZZ_4146				
Category: Cabinets	Location:	Description: Cabinet scratches on uppers left of oven		Incomplete
Partner: Cabinet Connection	Type:			
Code: ZZ_4147				
Category: Cabinets	Location:	Description: Cabinet scratches around fridge surround and on door faces above fridge surround		Incomplete
Partner: Cabinet Connection	Type:			
Code: ZZ_4148				
Category: Cabinets	Location:	Description: Cabinet scratches on fronts of all doors and drawers on kitchen island		Incomplete
Partner: Cabinet Connection	Type:			
Code: ZZ_4149				
Category: Cabinets	Location:	Description: Missing scribe on either side of kitchen island		Incomplete
Partner: Cabinet Connection	Type:			

Code: ZZ_4150	Location:		
Category: Cabinets	Type:	Description: Missing twe on all cabinets in kitchen	Incomplete
Partner: Cabinet Connection			
Code: ZZ_4163	Location:		
Category: Cabinets	Type:	Description: Twe missing In master bathroom	Incomplete
Partner: Cabinet Connection			
Code: ZZ_4164	Location:		
Category: Cabinets	Type:	Description: Cabinet scratches on right vanity faces in master bathroom	Incomplete
Partner: Cabinet Connection			
Code: ZZ_4165	Location:		
Category: Cabinets	Type:	Description: Cabinet scratches on left vanity faces in master bath	Incomplete
Partner: Cabinet Connection			
Code: ZZ_4166	Location:		
Category: Cabinets	Type:	Description: Center cabinet in master bathroom has lots of scratches on top and face of doors	Incomplete
Partner: Cabinet Connection			
Code: ZZ_4170	Location:		
Category: Cabinets	Type:	Description: Missing twe in bath 2	Incomplete
Partner: Cabinet Connection			
Code: ZZ_4171	Location:		
Category: Cabinets	Type:	Description: Latge gap at bottom of cabinet in bath 2	Incomplete
Partner: Cabinet Connection			
Code: ZZ_4172	Location:		
Category: Cabinets	Type:	Description: Touch up on fronts of cabinet in bath 2	Incomplete
Partner: Cabinet Connection			
 Elia Painting			
Code: ZZ_4156	Location:		
Category: Paint	Type:	Description: Paint touch up around back slider	Incomplete
Partner: Elia Painting			

Code: ZZ_4158	Location:	Description: Paint touch up on with window in great room	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_4160	Location:	Description: Paint touch up around window in master bedroom	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_4161	Location:	Description: Paint touch up on wall opposite of window	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_4167	Location:	Description: Paint touch up in entry hall	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_4176	Location:	Description: Paint touch up on exterior of ho	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
<div></div> Fenceworks			
Code: ZZ_4174	Location:	Description: Fence not installed	Incomplete
Category: Fence	Type:		
Partner: Fenceworks			
<div></div> Ferguson			
Code: ZZ_4151	Location:	Description: Missing all appliances	Incomplete
Category: Appliances	Type:		
Partner: Ferguson			
<div></div> Landscape Connection			
Code: ZZ_4173	Location:	Description: Missing landscaping in front yard	Incomplete
Category: Landscaping	Type:		
Partner: Landscape Connection			

Code: ZZ_4175	Location:		
Category: Landscaping	Type:	Description: Drainage not installed in backyard	Incomplete
Partner: Landscape Connection			
<div><div></div>Ohanians Drywall</div>			
Code: ZZ_4153	Location:		
Category: Drywall	Type:	Description: Drywall touch up by fridge box	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_4154	Location:		
Category: Drywall	Type:	Description: Drywall by window in kitchen	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_4155	Location:		
Category: Drywall	Type:	Description: Crack in corner of dining room	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_4157	Location:		
Category: Drywall	Type:	Description: Crack in corner of great room	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_4159	Location:		
Category: Drywall	Type:	Description: Drywall crack in corner of master bedroom	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_4168	Location:		
Category: Drywall	Type:	Description: Cracks in corners of bed 2	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_4169	Location:		
Category: Drywall	Type:	Description: Corners of room has cracks in bed 3	Incomplete
Partner: Ohanians Drywall			
<div><div></div>Quality Plumbing</div>			

All Defects		Lot 7/Tract 6100	
Code: ZZ_4152			
Category: Plumbing	Location:	Description: Missing kitchen faucet	Incomplete
Partner: Quality Plumbing	Type:		
Code: ZZ_4162			
Category: Plumbing	Location:	Description: Rain shower head not installed	Incomplete
Partner: Quality Plumbing	Type:		
Code: ZZ_4177			
Category: Plumbing	Location:	Description: Set water heater	Incomplete
Partner: Quality Plumbing	Type:		