

Lot 1/Tract 1812	Items: 5	CH Items: 2	Checklist Inspections: 0
------------------	----------	-------------	-----------------------------

Central Valley Rain Gutters

Code: ZZ_092	Location: Backyard	Description: Gutter down spout by patio - there's a drain but no down spout	Complete
Category: Rain Gutters	Type: Not connected to drain system		
Partner: Central Valley Rain Gutters			

Code: ZZ_093	Location: Backyard	Description: Other gutter downspout spout is not connected to drain by patio	Complete
Category: Rain Gutters	Type: Not connected to drain system		
Partner: Central Valley Rain Gutters			

Code: ZZ_097	Location: Backyard	Description: Gutter down spout missing in side yard	Complete
Category: Rain Gutters	Type: Not connected to drain system		
Partner: Central Valley Rain Gutters			

Landscape Connection

Code: ZZ_095	Location: Backyard	Description: Gutter downspout by man - door is not connected to drain vent	CRITICAL Complete
Category: Landscaping	Type: Man door gutter downspout not connected to drain		
Partner: Landscape Connection			

Tri Valley Plastering & Drywall

Code: ZZ_094	Location: Backyard	Description: Remove stucco from bathroom drain clean out	CRITICAL Complete
Category: Stucco	Type: Stucco over the drain needs to be removed		
Partner: Tri Valley Plastering & Drywall			