De Young Properties

Lot 535/Tract 0273	Items: 22	CH Items: 0	Checklist Inspections: 0		
Cabinet Connection					
Code: ZZ_1331 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet missing trim or other parts	Description: Twe missing in kitchen	Complete		
Code: ZZ_1332 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet drawers and/or doors need to be adjusted	Description: Door under sink rubs	Complete		
Code: ZZ_1333 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on door on island	Complete		
Code: ZZ_1334 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on crown above fridge surround	Complete		
Code: ZZ_1335 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on fridge surround	Complete		
Code: ZZ_1336 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on door right of fridge surround	Complete		

Lot 535/Tract 0273	Items: 22	CH Items: 0	Checklist Inspections: 0
Code: ZZ_1337 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on crown right imof microwave	Complete
Code: ZZ_1338 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet missing trim or other parts	Description: Missing scribe left of island	Complete
Code: ZZ_1341 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on door left vanity	Complete
Code: ZZ_1342 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on door right vanity	Complete
Code: ZZ_1343 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on drawer in center	Complete
Code: ZZ_1344 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Issues with cabinet drawers and/or doors functionality	Description: Adjust drawers in center vanity	Complete
Code: ZZ_1346 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 2 Type: Cabinet missing trim or other parts	Description: Missing Twe	Complete

Lot 535/Tract 0273	Items: 22	CH Items: 0	Checklist Inspections: 0
Code: ZZ_1347			
Category: Cabinets	Location: Bathroom 2	Description: Missing scribe	Complete
Partner: Cabinet Connection	Type: Cabinet missing trim or other parts		
Code: ZZ_1348			
Category: Cabinets	Location: Bathroom 2	Description: Missing hinges on door	Complete
Partner: Cabinet Connection	Type: Cabinet missing trim or other parts		
Code: ZZ_1349			
Category: Cabinets	Location: Bathroom 2	Description: Scratches on sides and face of doors	Complete
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets		
Central Valley Rai	in Gutters		
Code: ZZ_1352			
Category: Rain Gutters	Location: Exterior	Description: Rain gutter not connected in back yard	Complete
Partner: Central Valley Rain Gutters	Type: Scratches		
Elia Painting			
Code: ZZ_1339	Location: Great Room		Complete
Category: Paint	Type: Caulking touch-up required at	Description: Crack in caulking by great room and baseboard	
Partner: Elia Painting	baseboard, window frame, trim/door frame, or wall corners		
Code: ZZ_1340			
Category: Paint	Location: Bedroom 1	Description: Paint touch up by coax	Complete
Partner: Elia Painting	Type: Touch-up required		
Code: ZZ_1345			
Category: Paint	Location: Entryway	Description: Touch up needed by light switch	Complete
Partner: Elia Painting	Type: Touch-up required		·



LinkUs

Code: ZZ_1350

Category: Low Voltage Electrical

Location: Bedroom 3 Type: Low voltage/data jacks missing or

not functional

Partner: LinkUs

Description: Missing

access point in closet

Complete

MV Style Electric

Code: ZZ_1351

Category: Electrical

Partner: MV Style

Electric

Location: Exterior

Type: Light fixture, or pieces of light

fixture, are missing

Description: Missing

doorbell

Complete