

All Defects		Lot 35/Tract 6164		
<div><div></div>Anlin Windows</div>				
Code: ZZ_1941		Location:		
Category: Windows		Type:	Description: Scratch on window in bed 3	Incomplete
Partner: Anlin Windows				
<div><div></div>Cabinet Connection</div>				
Code: ZZ_1946		Location:		
Category: Cabinets		Type:	Description: Cabinet touch up in kitchen by fridge surround	Incomplete
Partner: Cabinet Connection				
Code: ZZ_1947		Location:		
Category: Cabinets		Type:	Description: Secure scribe to side of island in kitchen	Incomplete
Partner: Cabinet Connection				
Code: ZZ_1954		Location:		
Category: Cabinets		Type:	Description: Cabinet scratches in master bathroom	Incomplete
Partner: Cabinet Connection				
Code: ZZ_1957		Location:		
Category: Cabinets		Type:	Description: Clip nails on side of counter where oven is to be installed	Incomplete
Partner: Cabinet Connection				
<div><div></div>Elia Painting</div>				
Code: ZZ_1940		Location:		
Category: Paint		Type:	Description: Paint touch up in bed 3	Incomplete
Partner: Elia Painting				
Code: ZZ_1942		Location:		
Category: Paint		Type:	Description: Paint touch up on bottom of door trim in bed 3	Incomplete
Partner: Elia Painting				

Code: ZZ_1943	Location:		
Category: Paint	Type:	Description: Paint touch up in bed 2 closet	Incomplete
Partner: Elia Painting			
Code: ZZ_1944	Location:		
Category: Paint	Type:	Description: Paint touch up in hall	Incomplete
Partner: Elia Painting			
Code: ZZ_1948	Location:		
Category: Paint	Type:	Description: Lots of paint touch up in hall by kitchen	Incomplete
Partner: Elia Painting			
Code: ZZ_1949	Location:		
Category: Paint	Type:	Description: Paint touch up in dining nook	Incomplete
Partner: Elia Painting			
Code: ZZ_1950	Location:		
Category: Paint	Type:	Description: Paint touch up in great room	Incomplete
Partner: Elia Painting			
Code: ZZ_1951	Location:		
Category: Paint	Type:	Description: Paint touch up in hall by master	Incomplete
Partner: Elia Painting			
Code: ZZ_1952	Location:		
Category: Paint	Type:	Description: Paint touch in master	Incomplete
Partner: Elia Painting			
Code: ZZ_1955	Location:		
Category: Paint	Type:	Description: Paint touch up in master closet	Incomplete
Partner: Elia Painting			
Code: ZZ_1956	Location:		
Category: Paint	Type:	Description: Paint touch up in laundry room	Incomplete
Partner: Elia Painting			



Code: ZZ_1966	Location:		
Category: Fence	Type:	Description: Finish install of fence	Incomplete
Partner: Fenceworks			
<div><div></div>Ferguson</div>			
Code: ZZ_1961	Location:		
Category: Appliances	Type:	Description: Install oven and dishwasher	Incomplete
Partner: Ferguson			
<div><div></div>Fresno Shower Door & Mirror</div>			
Code: ZZ_1953	Location:		
Category: Shower Door & Mirror	Type:	Description: Missing shower enclosure in master bath	Incomplete
Partner: Fresno Shower Door & Mirror			
<div><div></div>LinkUs</div>			
Code: ZZ_1965	Location:		
Category: Low Voltage Electrical	Type:	Description: Install blank exterior plates for speaker pre wires	Incomplete
Partner: LinkUs			
<div><div></div>Quality Plumbing</div>			
Code: ZZ_1958	Location:		
Category: Plumbing	Type:	Description: Finish install of air button	Incomplete
Partner: Quality Plumbing			
<div><div></div>Simas Flooring & Design</div>			
Code: ZZ_1945	Location:		
Category: Carpet / Hardwood / Laminate	Type:	Description: Gap in hall by baseboard	Incomplete
Partner: Simas Flooring & Design			

Code: ZZ_1959				
Category: Carpet / Hardwood / Laminate	Location:		Description: Gap in laminate by slider	Incomplete
	Type:			
Partner: Simas Flooring & Design				
Code: ZZ_1960				
Category: Carpet / Hardwood / Laminate	Location:		Description: Gap in transition strip to kitchen from hall	Incomplete
	Type:			
Partner: Simas Flooring & Design				
<div><div></div>Tri Valley Plastering & Drywall</div>				
Code: ZZ_1962				
Category: Stucco	Location:		Description: Stucco touch up bath communication box	Incomplete
	Type:			
Partner: Tri Valley Plastering & Drywall				
Code: ZZ_1963				
Category: Stucco	Location:		Description: Stucco touch up around lower condensation line	Incomplete
	Type:			
Partner: Tri Valley Plastering & Drywall				
Code: ZZ_1964				
Category: Stucco	Location:		Description: Stucco touch up back patio holes were drilled and bottom footing is chipping off	Incomplete
	Type:			
Partner: Tri Valley Plastering & Drywall				