


Lot 4/Tract 6377	Items: 43	CH Items: 2	Checklist Inspections: 287
------------------	-----------	-------------	----------------------------------

<div><div></div>Anlin Windows</div>			
Code: ZZ_1700			
Category: Windows	Location: Great Room	Description: Scratches on slider	Incomplete
Partner: Anlin Windows	Type: Window glass has scratches		
Code: ZZ_1701			
Category: Windows	Location: Great Room	Description: Scratches on slider frame	Incomplete
Partner: Anlin Windows	Type: Window frame has scratches/chips/gouges		
<div><div></div>Cabinet Connection</div>			
Code: ZZ_1674			
Category: Cabinets	Location: Bathroom 1	Description: Scratches on doors on right side of vanity	Incomplete
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets		
Code: ZZ_1675			
Category: Cabinets	Location: Bathroom 1	Description: Scratches on drawers	Incomplete
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets		
Code: ZZ_1676			
Category: Cabinets	Location: Bathroom 1	Description: Scratches on doors left side of vanity	Incomplete
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets		
Code: ZZ_1690			
Category: Cabinets	Location: Kitchen	Description: Touch up around fridge surround	Incomplete
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks		

Code: ZZ_1691	Location: Kitchen		
Category: Cabinets	Type: Cabinets have scratches, chips, and/or cracks	Description: Touch up on drawers left of oven	Incomplete
Partner: Cabinet Connection			
Code: ZZ_1692	Location: Kitchen		
Category: Cabinets	Type: Cabinets have scratches, chips, and/or cracks	Description: Touch up on lower left cabinet doors	Incomplete
Partner: Cabinet Connection			
Code: ZZ_1693	Location: Kitchen		
Category: Cabinets	Type: Cabinets have scratches, chips, and/or cracks	Description: Touch up on upper left cabinet doors	Incomplete
Partner: Cabinet Connection			
Code: ZZ_1694	Location: Kitchen		
Category: Cabinets	Type: Cabinets have scratches, chips, and/or cracks	Description: Crown seam needs touch up	Incomplete
Partner: Cabinet Connection			
Code: ZZ_1695	Location: Kitchen		
Category: Cabinets	Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on drawers on island	Incomplete
Partner: Cabinet Connection			
Code: ZZ_1696	Location: Kitchen		
Category: Cabinets	Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on doors under sink	Incomplete
Partner: Cabinet Connection			
 Elia Painting			
Code: ZZ_1678	Location: Bathroom 1		
Category: Paint	Type: Touch-up required	Description: Paint touch up by base right of cabinets	Incomplete
Partner: Elia Painting			
Code: ZZ_1679	Location: Bathroom 1		
Category: Paint	Type: Touch-up required	Description: Paint touch up on wall under towel bar	Incomplete
Partner: Elia Painting			

Code: ZZ_1680			
Category: Paint	Location: Bedroom 1	Description: Paint drip on baseboard	Incomplete
Partner: Elia Painting	Type: Touch-up required		
Code: ZZ_1683			
Category: Paint	Location: Bedroom 2	Description: Paint by base on right side as you enter	Incomplete
Partner: Elia Painting	Type: Touch-up required		
Code: ZZ_1684			
Category: Paint	Location: Bedroom 2	Description: Paint touch up on window sill	Incomplete
Partner: Elia Painting	Type: Touch-up required		
Code: ZZ_1685			
Category: Paint	Location: Bedroom 2	Description: Paint touch up on closet door	Incomplete
Partner: Elia Painting	Type: Touch-up required		
Code: ZZ_1687			
Category: Paint	Location: Bedroom 3	Description: Paint touch up on bullnose	Incomplete
Partner: Elia Painting	Type: Touch-up required		
Code: ZZ_1688			
Category: Paint	Location: Bedroom 3	Description: Paint touch up on closet door	Incomplete
Partner: Elia Painting	Type: Touch-up required		
Code: ZZ_1689			
Category: Paint	Location: Bedroom 3	Description: Paint touch up on baseboard around room	Incomplete
Partner: Elia Painting	Type: Touch-up required		
Code: ZZ_1699			
Category: Paint	Location: Great Room	Description: Paint discoloration around great room	Incomplete
Partner: Elia Painting	Type: Touch-up required		

Code: ZZ_1702			
Category: Paint	Location: Hallway	Description: Touch up on bullnose	Incomplete
Partner: Elia Painting	Type: Touch up		
Code: ZZ_1703			
Category: Paint	Location: Hallway	Description: Touch up on baseboard	Incomplete
Partner: Elia Painting	Type: Touch up		
Code: ZZ_1704			
Category: Paint	Location: Hallway	Description: Touch up on door to garage	Incomplete
Partner: Elia Painting	Type: Touch up		
Code: ZZ_1705			
Category: Paint	Location: Hallway	Description: Touch up on wall left of laundry room	Incomplete
Partner: Elia Painting	Type: Touch up		
Code: ZZ_1708			
Category: Paint	Location: Laundry Room	Description: Paint touch up under upper cabinets	Incomplete
Partner: Elia Painting	Type: Touch-up required		
Code: ZZ_1709			
Category: Paint	Location: Laundry Room	Description: Paint touch up above baseboard by light switches	Incomplete
Partner: Elia Painting	Type: Touch-up required		
Code: ZZ_1711			
Category: Paint	Location: Exterior	Description: Paint front door	Incomplete
Partner: Elia Painting	Type: Stucco pop-out, shutters and/or deco vents, or fascia paint issues		
Code: ZZ_1712			
Category: Paint	Location: Exterior	Description: Paint siding	Incomplete
Partner: Elia Painting	Type: Stucco pop-out, shutters and/or deco vents, or fascia paint issues		

<div>Code: ZZ_1713</div> <div>Category: Paint</div> <div>Partner: Elia Painting</div>	<div>Location: Exterior</div> <div>Type: Stucco pop-out, shutters and/or deco vents, or fascia paint issues</div>	<div>Description: Paint pop outs</div>	<div>Incomplete</div>
<div>Code: ZZ_1714</div> <div>Category: Paint</div> <div>Partner: Elia Painting</div>	<div>Location: Exterior</div> <div>Type: Stucco pop-out, shutters and/or deco vents, or fascia paint issues</div>	<div>Description: Paint shutters</div>	<div>Incomplete</div>
<div><div></div><div>Fenceworks</div></div>			
<div>Code: ZZ_1715</div> <div>Category: Fence</div> <div>Partner: Fenceworks</div>	<div>Location: Exterior</div> <div>Type: Warped</div>	<div>Description: Trim gate on side yard</div>	<div>Incomplete</div>
<div><div></div><div>Ferguson</div></div>			
<div>Code: ZZ_1697</div> <div>Category: Appliances</div> <div>Partner: Ferguson</div>	<div>Location: Kitchen</div> <div>Type: Scratch(es)</div>	<div>Description: Dent on microwave</div>	<div>Incomplete</div>
<div>Code: ZZ_1698</div> <div>Category: Appliances</div> <div>Partner: Ferguson</div>	<div>Location: Kitchen</div> <div>Type: Appliance(s) missing</div>	<div>Description: Missing</div>	<div>CRITICAL Incomplete</div>
<div><div></div><div>Ideal Custom Tile</div></div>			
<div>Code: ZZ_1706</div> <div>Category: Tile</div> <div>Partner: Ideal Custom Tile</div>	<div>Location: Hallway</div> <div>Type: Crack or chipped tile</div>	<div>Description: Grout missing by closet door</div>	<div>Incomplete</div>
<div>Code: ZZ_1707</div> <div>Category: Tile</div> <div>Partner: Ideal Custom Tile</div>	<div>Location: Laundry Room</div> <div>Type: Grout at tile is cracked, missing, wrong color, and/or needs touch-up</div>	<div>Description: Grout missing by door to laundry room</div>	<div>Incomplete</div>

<div></div> Landscape Connection
----------------------------------

Code: ZZ_1716			
Category: Landscaping	Location: Exterior	Description: Landscape not installed	CRITICAL Incomplete
Partner: Landscape Connection	Type: Missing		

<div></div> Ohanians Drywall
------------------------------

Code: ZZ_1682			
Category: Drywall	Location: Bathroom 2	Description: Drywall texture by tile shower	Incomplete
Partner: Ohanians Drywall	Type: Drywall texture issues		

Code: ZZ_1686			
Category: Drywall	Location: Bedroom 3	Description: Drywall booger’s behind door	Incomplete
Partner: Ohanians Drywall	Type: Drywall texture issues		

Code: ZZ_1710			
Category: Drywall	Location: Laundry Room	Description: Drywall lines right of cabinets	Incomplete
Partner: Ohanians Drywall	Type: Drywall texture issues		

<div></div> Westech
---------------------

Code: ZZ_1677			
Category: Electrical	Location: Bathroom 1	Description: Missing light bulbs on left vanity	Incomplete
Partner: Westech	Type: Light fixtures, or pieces of light fixtures, are missing		

Code: ZZ_1681			
Category: Electrical	Location: Bathroom 2	Description: Missing light bulbs	Incomplete
Partner: Westech	Type: Light fixtures, or pieces of light fixtures, are missing		