De Young Properties

All Defects	Lot 21/Tract 6100		
Cabinet Connection			
Code: ZZ_4126 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Missing upper cabinet doors to the right of oven	Incomplete
Code: ZZ_4127 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Scratch on dwb face	Incomplete
Code: ZZ_4128 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Scratches on uppers and lowers to the left of oven	Incomplete
Code: ZZ_4129 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Scratches and blemishes on uppers and lowers around fridge surround	Incomplete
Code: ZZ_4130 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Scratches on cabinet faces on kitchen island	Incomplete
Code: ZZ_4131 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Cabinet scratches on faces of doors and drawers in bath 2	Incomplete
Code: ZZ_4132 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Cabinet scratches on doors and drawers in bath 3	Incomplete
Code: ZZ_4133 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Adjust cabinet drawers in master bath are rubbing	Incomplete

All Defects Lot 21/Tract 6100 Code: ZZ_4134 Location: Description: Cabinet scratches on faces of left and right vanity's in master bathroom Category: Cabinets Incomplete

Type:

Partner: Cabinet Connection