

Lot 150/Tract 0273	Items: 21	CH Items: 3	Checklist Inspections: 235
--------------------	-----------	-------------	----------------------------

<div><div></div>Anlin Windows</div>			
Code: ZZ_865			
Category: Windows	Location: Dining Room	Description: Please address window in dining room not sliding	<div>CRITICAL</div> Incomplete
Partner: Anlin Windows	Type: Window lock is not installed and/or is not working		
Code: ZZ_869			
Category: Windows	Location: Bedroom 1	Description: Left window not opening correctly	<div>CRITICAL</div> Incomplete
Partner: Anlin Windows	Type: Window lock is not installed and/or is not working		
Code: ZZ_870			
Category: Windows	Location: Bedroom 1	Description: Large window not opening correctly	<div>CRITICAL</div> Incomplete
Partner: Anlin Windows	Type: Window lock is not installed and/or is not working		
<div><div></div>Cabinet Connection</div>			
Code: ZZ_866			
Category: Cabinets	Location: Bathroom 1	Description: Blemish on right cabinet door on right vanity	<div>Incomplete</div>
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets		
Code: ZZ_867			
Category: Cabinets	Location: Bathroom 1	Description: Blemishes on left cabinet doors	<div>Incomplete</div>
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets		
Code: ZZ_873			
Category: Cabinets	Location: Kitchen	Description: Scratch on top part of cabinet door to the right of oven	<div>Incomplete</div>
Partner: Cabinet Connection	Type: Cabinet missing trim or other parts		

Code: ZZ_874			
Category: Cabinets	Location: Kitchen	Description: Blemishes on faces of doors on island left of sink	Incomplete
	Type: Cabinet missing trim or other parts		
Partner: Cabinet Connection			
Code: ZZ_875			
Category: Cabinets	Location: Kitchen	Description: Bubble on false front under kitchen sink	Incomplete
	Type: Cabinet missing trim or other parts		
Partner: Cabinet Connection			
Code: ZZ_876			
Category: Cabinets	Location: Kitchen	Description: Blemishes on fridge surround	Incomplete
	Type: Cabinet missing trim or other parts		
Partner: Cabinet Connection			
Code: ZZ_877			
Category: Cabinets	Location: Kitchen	Description: Missing scribe around island	Incomplete
	Type: Cabinet missing trim or other parts		
Partner: Cabinet Connection			
Code: ZZ_878			
Category: Cabinets	Location: Bathroom 2	Description: Scratches on face of cabinets	Incomplete
	Type: Scratches/chips/cracks/gouges in cabinets		
Partner: Cabinet Connection			
<div><div></div>Elia Painting</div>			
Code: ZZ_871			
Category: Paint	Location: Bedroom 1	Description: Paint touch up on ceiling by light	Incomplete
	Type: Touch-up required		
Partner: Elia Painting			
<div><div></div>MV Style Electric</div>			

Code: ZZ_868			
Category: Electrical	Location: Bathroom 1	Description: Missing vanity light on right side vanity	Incomplete
Partner: MV Style Electric	Type: Light fixtures, or pieces of light fixtures, are missing		
Code: ZZ_872			
Category: Electrical	Location: Bedroom 1	Description: Light is flickering	Incomplete
Partner: MV Style Electric	Type: Electrical outlets missing or not functional		
Code: ZZ_882			
Category: Electrical	Location: Bedroom 2	Description: Missing bulb in light fixture	Incomplete
Partner: MV Style Electric	Type: Light fixture, or pieces of light fixture, are missing		
Ohanians Drywall			
Code: ZZ_881			
Category: Drywall	Location: Bedroom 3	Description: Drywall crack by corner	Incomplete
Partner: Ohanians Drywall	Type: Drywall has crack, gash, hole, and/or gouge		
Quality Plumbing			
Code: ZZ_880			
Category: Plumbing	Location: Bathroom 2	Description: Scratches on bath tub	Incomplete
Partner: Quality Plumbing	Type: Defect(s) in Bath/Shower fitter/surround		
Tri Valley Plastering & Drywall			
Code: ZZ_883			
Category: Stucco	Location: Exterior	Description: Fog patches on corner of front of home	Incomplete
Partner: Tri Valley Plastering & Drywall	Type: Inconsistent Fog coat		

Code: ZZ_884

Category: Stucco	Location: Exterior	Description: Fog footing left of home	Incomplete
Partner: Tri Valley Plastering & Drywall	Type: Inconsistent Fog coat		

Code: ZZ_885

Category: Stucco	Location: Exterior	Description: Stucco hole by condenser in back yard	Incomplete
Partner: Tri Valley Plastering & Drywall	Type: Chip/crack/gouge		

 Visalia Tile

Code: ZZ_879

Category: Tile	Location: Bathroom 2	Description: Grout crack by bathtub	Incomplete
	Type: Grout at tile is cracked, missing, wrong color, and/or needs touch-up		
Partner: Visalia Tile			