

Lot 354/Tract 0273	Items: 16	CH Items: 0	Checklist Inspections: 215
--------------------	-----------	-------------	----------------------------

<div></div> Anlin Windows			
Code: ZZ_899			
Category: Windows	Location: Bedroom 2	Description: Missing screens on all windows	Incomplete
Partner: Anlin Windows	Type: Window missing a screen		
<div></div> Cabinet Connection			
Code: ZZ_889			
Category: Cabinets	Location: Bathroom 1	Description: Scratches on left cabinet doors	Incomplete
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets		
Code: ZZ_890			
Category: Cabinets	Location: Bathroom 1	Description: Scratches on right cabinet doors on right vanity	Incomplete
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets		
Code: ZZ_891			
Category: Cabinets	Location: Kitchen	Description: Address scratches on bottom cabinets right of oven	Incomplete
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks		
Code: ZZ_892			
Category: Cabinets	Location: Kitchen	Description: Scratches on cabinet face right of microwave	Incomplete
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks		
Code: ZZ_893			
Category: Cabinets	Location: Kitchen	Description: Cabinet door face left of oven scratches	Incomplete
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks		

Code: ZZ_894			
Category: Cabinets	Location: Kitchen	Description: Fridge surround scratches	Incomplete
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks		
Code: ZZ_896			
Category: Cabinets	Location: Bathroom 2	Description: Scratches on cabinet faces on vanity	Incomplete
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets		
<div><div></div> Elia Painting</div>			
Code: ZZ_887			
Category: Paint	Location: Bedroom 1	Description: Paint touch up by coax	Incomplete
Partner: Elia Painting	Type: Touch-up required		
Code: ZZ_888			
Category: Paint	Location: Bedroom 1	Description: Paint touch up by outlet	Incomplete
Partner: Elia Painting	Type: Touch-up required		
Code: ZZ_898			
Category: Paint	Location: Bedroom 2	Description: Paint touch up by outlet on back wall	Incomplete
Partner: Elia Painting	Type: Touch-up required		
<div><div></div> Fenceworks</div>			
Code: ZZ_901			
Category: Fence	Location: Exterior	Description: Missing fence section	Incomplete
Partner: Fenceworks	Type: Warped		
<div><div></div> MV Style Electric</div>			

Code: ZZ_897				
Category: Electrical	Location: Bathroom 2		Description: Missing light switch plate cover	Incomplete
	Type: Light fixtures, or pieces of light fixtures, are missing			
Partner: MV Style Electric				
Code: ZZ_900				
Category: Electrical	Location: Exterior		Description: Missing carriage lights by garage	Incomplete
	Type: Light fixture, or pieces of light fixture, are missing			
Partner: MV Style Electric				
<div><div></div>Ohanians Drywall</div>				
Code: ZZ_886				
Category: Drywall	Location: Great Room		Description: 2 pin holes by outlet	Incomplete
	Type: Drywall has crack, gash, hole, and/or gouge			
Partner: Ohanians Drywall				
<div><div></div>Quality Plumbing</div>				
Code: ZZ_895				
Category: Plumbing	Location: Bathroom 2		Description: Crack in tub	Incomplete
	Type: Defect(s) in Bath/Shower fitter/surround			
Partner: Quality Plumbing				