De Young Properties

Lot 535/Tract 0273	Items: 23	CH Items: 0	Checklist Inspections: 0		
Cabinet Connection					
Code: ZZ_1331 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet missing trim or other parts	Description: Twe missing in kitchen	Complete		
Code: ZZ_1332 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet drawers and/or doors need to be adjusted	Description: Door under sink rubs	Complete		
Code: ZZ_1333 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on door on island	Complete		
Code: ZZ_1334 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on crown above fridge surround	Complete		
Code: ZZ_1335 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on fridge surround	Complete		
Code: ZZ_1336 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on door right of fridge surround	Complete		

Lot 535/Tract 0273	Items: 23	CH Items: 0	Checklist Inspections: 0
Code: ZZ_1337 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on crown right imof microwave	Complete
Code: ZZ_1338 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet missing trim or other parts	Description: Missing scribe left of island	Complete
Code: ZZ_1341 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on door left vanity	Complete
Code: ZZ_1342 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on door right vanity	Complete
Code: ZZ_1343 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on drawer in center	Complete
Code: ZZ_1344 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Issues with cabinet drawers and/or doors functionality	Description: Adjust drawers in center vanity	Complete
Code: ZZ_1346 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 2 Type: Cabinet missing trim or other parts	Description: Missing Twe	Complete

Lot 535/Tract 0273	Items: 23	CH Items: 0	Checklist Inspections: 0
Code: ZZ_1347 Category: Cabinets Partner: Cabinet	Location: Bathroom 2 Type: Cabinet missing trim or other parts	Description: Missing scribe	Complete
Connection Code: ZZ_1348 Category: Cabinets Partner: Cabinet	Location: Bathroom 2 Type: Cabinet missing trim or other parts	Description: Missing hinges on door	Complete
Connection Code: ZZ_1349 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 2 Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on sides and face of doors	Complete
Central Valley Ra Code: ZZ_1352 Category: Rain Gutters Partner: Central Valley Rain Gutters	Location: Exterior Type: Scratches	Description: Rain gutter not connected in back yard	Complete
Elia Painting Code: ZZ_1339 Category: Paint Partner: Elia Painting	Location: Great Room Type: Caulking touch-up required at baseboard, window frame, trim/door frame, or wall corners	Description: Crack in caulking by great room and baseboard	Complete
Code: ZZ_1340 Category: Paint Partner: Elia Painting	Location: Bedroom 1 Type: Touch-up required	Description: Paint touch up by coax	Complete
Code: ZZ_1345 Category: Paint Partner: Elia Painting	Location: Entryway Type: Touch-up required	Description: Touch up needed by light switch	Complete

Category: Millwork Location: Bedroom 3

Code: ZZ 1353

Partner: Premier

Door

Type: Door trim has chip, gash, gouge, cut

too short near flooring or is missing

Description: Broken

closet door

Incomplete