



Lot 14/Tract 6349		Items: 18	CH Items: 1	Checklist Inspections: 211
<div><div></div>Cabinet Connection</div>				
Code: ZZ_906	Location: Bathroom 1	Description: Paint smudge on right drawer	Incomplete	
Category: Cabinets	Type: Scratches/chips/cracks/gouges in cabinets			
Partner: Cabinet Connection				
Code: ZZ_907	Location: Bathroom 1	Description: Paint smudge on center vanity	Incomplete	
Category: Cabinets	Type: Scratches/chips/cracks/gouges in cabinets			
Partner: Cabinet Connection				
Code: ZZ_908	Location: Bathroom 1	Description: Smudges on top plate	Incomplete	
Category: Cabinets	Type: Scratches/chips/cracks/gouges in cabinets			
Partner: Cabinet Connection				
Code: ZZ_909	Location: Bathroom 1	Description: False front crooked	Incomplete	
Category: Cabinets	Type: Issues with cabinet drawers and/or doors functionality			
Partner: Cabinet Connection				
Code: ZZ_913	Location: Kitchen	Description: Need cover on hindges on corner cabinet	Incomplete	
Category: Cabinets	Type: Cabinet drawers and/or doors need to be adjusted			
Partner: Cabinet Connection				
<div><div></div>Central Valley Rain Gutters</div>				
Code: ZZ_918	Location: Exterior	Description: Rain gutter dented by ac condenser	Incomplete	
Category: Rain Gutters	Type: Scratches			
Partner: Central Valley Rain Gutters				
<div><div></div>Elia Painting</div>				

Lot 14/Tract 6349		Items: 18	CH Items: 1	Checklist Inspections: 211
Code: ZZ_902				
Category: Paint	Location: Den		Description: Paint touch up by light switches	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: ZZ_903				
Category: Paint	Location: Den		Description: Tape line above base showing	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: ZZ_904				
Category: Paint	Location: Den		Description: Paint around outlet	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: ZZ_905				
Category: Paint	Location: Bedroom 1		Description: Paint touch up on back wall	Incomplete
Partner: Elia Painting	Type: Touch-up required			
<div><div></div>Fenceworks</div>				
Code: ZZ_915				
Category: Fence	Location: Exterior		Description: Trim bottom of fence on side yard	Incomplete
Partner: Fenceworks	Type: Warped			
Code: ZZ_919				
Category: Fence	Location: Exterior		Description: Fence missing	Incomplete
Partner: Fenceworks	Type: Warped			
<div><div></div>Ideal Custom Tile</div>				
Code: ZZ_911				
Category: Tile	Location: Bathroom 1		Description: Tile not cut correctly around handle	Incomplete
Partner: Ideal Custom Tile	Type: Missing tile			

Lot 14/Tract 6349		Items: 18	CH Items: 1	Checklist Inspections: 211
Code: ZZ_912		Location: Great Room	Description: Grout touch up by baseboard	Incomplete
Category: Tile		Type: Grout at tile is cracked, missing, wrong color, and/or needs touch-up		
Partner: Ideal Custom Tile				
Code: ZZ_914		Location: Bathroom 2	Description: Grout tile by bathtub	Incomplete
Category: Tile		Type: Grout at tile is cracked, missing, wrong color, and/or needs touch-up		
Partner: Ideal Custom Tile				
 Quality Plumbing				
Code: ZZ_910		Location: Bathroom 1	Description: Caulking needed around bathtub	CRITICAL Incomplete
Category: Plumbing		Type: Caulking at tub		
Partner: Quality Plumbing				
 Tri Valley Plastering & Drywall				
Code: ZZ_916		Location: Exterior	Description: Stucco touch up right side of home by man door	Incomplete
Category: Stucco		Type: Chip/crack/gouge		
Partner: Tri Valley Plastering & Drywall				
Code: ZZ_917		Location: Exterior	Description: Stucco touch up back side of home	Incomplete
Category: Stucco		Type: Chip/crack/gouge		
Partner: Tri Valley Plastering & Drywall				