

All Defects				
<div><div></div>Central Valley Truss</div>				
<div><div>Code: ZZ_063</div><div>Category: Truss</div><div>Partner: Central Valley Truss</div><div>Location: Great Room</div><div>Type: Sagging trusses</div><div>Description: Test 5</div><div>Incomplete</div></div>				
<div><div></div>Quality Plumbing</div>				
<div><div>Code: ZZ_062</div><div>Category: Plumbing</div><div>Partner: Quality Plumbing</div><div>Location: Kitchen</div><div>Type: Garbage disposal operation</div><div>Description: Test 4</div><div>Incomplete</div></div>				
<div><div></div>Westech</div>				
<div><div>Code: ZZ_061</div><div>Category: Electrical</div><div>Partner: Westech</div><div>Location: Flex Den</div><div>Type:</div><div>Description: Test 3</div><div>Incomplete</div></div>				