

All Defects		Lot 8/Tract 6164		
<div><div></div>Cabinet Connection</div>				
Code: ZZ_1397		Location:	Description: Cabinet scratches on door faces in kitchen by stove top	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_1398		Location:	Description: Cabinet scratches in kitchen on door faces by sink	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
<div><div></div>Central Valley Rain Gutters</div>				
Code: ZZ_1428		Location:	Description: Replace dented gutter downspout on right side of home	Incomplete
Category: Rain Gutters		Type:		
Partner: Central Valley Rain Gutters				
<div><div></div>Elia Painting</div>				
Code: ZZ_1399		Location:	Description: Paint on kitchen cabinet right of stove top	Incomplete
Category: Paint		Type:		
Partner: Elia Painting				
Code: ZZ_1400		Location:	Description: Paint Mari on bullnose in landing by garage	Incomplete
Category: Paint		Type:		
Partner: Elia Painting				
Code: ZZ_1404		Location:	Description: Paint touch up on wall in great room	Incomplete
Category: Paint		Type:		
Partner: Elia Painting				
Code: ZZ_1405		Location:	Description: Paint in downstairs hall	Incomplete
Category: Paint		Type:		
Partner: Elia Painting				

Code: ZZ_1409	Location:	Description: Visible tape line in bed 4 by baseboard	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_1410	Location:	Description: Paint by downstairs door frame	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_1411	Location:	Description: Light paint on stair trim	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_1412	Location:	Description: Visible tape line in bed 2	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_1413	Location:	Description: Paint upstairs hall wall by bath 2 door	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_1415	Location:	Description: Paint in bath 2 by toilet	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_1416	Location:	Description: Paint corners of door in upstairs hall closet	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_1419	Location:	Description: Visible tape line in master by baseboard	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_1421	Location:	Description: Paint areas in master closet	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			

Code: ZZ_1426	Location:		
Category: Fence	Type:	Description: Install fence	Incomplete
Partner: Fenceworks			
<div><div></div>Ferguson</div>			
Code: ZZ_1430	Location:		
Category: Appliances	Type:	Description: Install appliances	Incomplete
Partner: Ferguson			
<div><div></div>G&G Concrete</div>			
Code: ZZ_1431	Location:		
Category: Concrete	Type:	Description: Fix concrete in garage	Incomplete
Partner: G&G Concrete			
<div><div></div>Ideal Custom Tile</div>			
Code: ZZ_1402	Location:		
Category: Tile	Type:	Description: Uneven tiles in bonus room	Incomplete
Partner: Ideal Custom Tile			
Code: ZZ_1414	Location:		
Category: Tile	Type:	Description: Grout crack in bath 2 by tub	Incomplete
Partner: Ideal Custom Tile			
Code: ZZ_1417	Location:		
Category: Tile	Type:	Description: Clean thunder off cabinet in laundry room	Incomplete
Partner: Ideal Custom Tile			
Code: ZZ_1420	Location:		
Category: Tile	Type:	Description: Grout tile kick in master bath under both vanities	Incomplete
Partner: Ideal Custom Tile			
Code: ZZ_1422	Location:		
Category: Tile	Type:	Description: Install drain in master shower pan	Incomplete
Partner: Ideal Custom Tile			

Code: ZZ_1423	Location:		
Category: Tile	Type:	Description: Grout tile by bed 4	Incomplete
Partner: Ideal Custom Tile			
Code: ZZ_1424	Location:		
Category: Tile	Type:	Description: Grout crack by bath 3 tub	Incomplete
Partner: Ideal Custom Tile			
<div></div> Landscape Connection			
Code: ZZ_1429	Location:		
Category: Landscaping	Type:	Description: Replace approximately 16 plants	Incomplete
Partner: Landscape Connection			
<div></div> Ohanians Drywall			
Code: ZZ_1401	Location:		
Category: Drywall	Type:	Description: Drywall booger and line by outlet next to bonus room	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_1403	Location:		
Category: Drywall	Type:	Description: Boogers on window sill in dining room	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_1408	Location:		
Category: Drywall	Type:	Description: Drywall line in bed 4	Incomplete
Partner: Ohanians Drywall			
<div></div> Tri Valley Plastering & Drywall			
Code: ZZ_1425	Location:		
Category: Stucco	Type:	Description: Stucco touch up around home exterior	Incomplete
Partner: Tri Valley Plastering & Drywall			

All Defects		Lot 8/Tract 6164		
Code: ZZ_1427				
Category: Stucco		Location:	Description: Repair cracked stucco by weep screed around whole home	Incomplete
Partner: Tri Valley Plastering & Drywall		Type:		
<div><div></div>Westech</div>				
Code: ZZ_1406				
Category: Electrical		Location:	Description: Missing outlets in kitchen	Incomplete
Partner: Westech		Type:		
Code: ZZ_1407				
Category: Electrical		Location:	Description: Missing screw in bed 4 outlet	Incomplete
Partner: Westech		Type:		
Code: ZZ_1418				
Category: Electrical		Location:	Description: Inspect smoke alarm upstairs is chirping	Incomplete
Partner: Westech		Type:		