

All Defects		Lot 34/Tract 6260		
<div><div></div>Anlin Windows</div>				
Code: ZZ_169				
Category: Windows	Location: Bedroom 2		Description: Window stops all need to be pushed in more in all rooms	Incomplete
Partner: Anlin Windows	Type: Window pane flawed			
Code: ZZ_176				
Category: Windows	Location: Great Room		Description: Great room screen at slider needs adjustment Great room slider doors need adjustment Great room slider frame needs some cleanup	Incomplete
Partner: Anlin Windows	Type: Window frame scratched/chipped/dented			
<div><div></div>Cabinet Connection</div>				
Code: ZZ_165				
Category: Cabinets	Location: Bathroom 2		Description: Bath 2 various chips in top of cabinets and inside of left drawer Right drawer needs adjustment	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)			
Code: ZZ_172				
Category: Cabinets	Location: Bathroom 1		Description: Various chips and scratches on cabinets in master shower Check alignment on doors and drawers	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)			
Code: ZZ_177				
Category: Cabinets	Location: Kitchen		Description: Kitchen various chips and scratches	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)			
Code: ZZ_178				
Category: Cabinets	Location: Kitchen		Description: Kitchen island missing top trim pieces under counter top	Incomplete
Partner: Cabinet Connection	Type: Part missing			

All Defects

Lot 34/Tract 6260

Code: ZZ_179

Category: Cabinets

Location: Laundry Room

Description: Laundry room cabinet chips and scratches

Incomplete

Partner: Cabinet Connection

Type: Dent(s), ding(s), scratch(es)

 Central Valley Overhead Door

Code: ZZ_182

Category: Garage Door


Location: Garage

Description: Ding/chip in garage door on interior side

Incomplete

Partner: Central Valley Overhead Door

Type: Dented panel(s)

 De Young Properties

Code: ZZ_164

Category: Paint

Location: Entryway

Description: Paint touch up behind front door Caulking in corner behind front door Paint touch up in half bath door itself Bedroom 3 door frame Bedroom 3 closet door and door frame

Incomplete

Partner: De Young Properties

Type: Chip/gouge/scratch

Code: ZZ_166

Category: Paint

Location: Bedroom 2

Description: Bed 2 door and sides of door need touch up Baseboard behind the door

Incomplete

Partner: De Young Properties

Type: Chip/gouge/scratch

Code: ZZ_167

Category: Paint

Location: Bedroom 4

Description: Bed 4 exterior door frame clean up Small hole next to outlet by closet

Incomplete

Partner: De Young Properties

Type: Chip/gouge/scratch

 Everlast Paint

Code: ZZ_168

Category: Paint

Location: Bathroom 2

Description: Bathroom 2 has a lot of dry wall much drips and paint drips

Incomplete

Partner: Everlast Paint

Type: Cleanup

All Defects		Lot 34/Tract 6260		
Code: ZZ_170				
Category: Paint	Location: Bedroom 1	Description: Clean off paint from closet rod in coat closet by master	Incomplete	
Partner: Everlast Paint	Type: Cleanup			
Code: ZZ_173				
Category: Paint	Location: Bedroom 1	Description: Paint touch various places on exterior door to master bedroom and door frame	Incomplete	
Partner: Everlast Paint	Type: Chip/gouge/scratch			
Code: ZZ_174				
Category: Paint	Location: Bedroom 1	Description: Caulking needed at master bedroom rear window	Incomplete	
Partner: Everlast Paint	Type: Cleanup			
<div></div> Ferguson				
Code: ZZ_183				
Category: Paint	Location: Kitchen	Description: Clean up paint on man door	Incomplete	
Partner: Ferguson	Type: Cleanup			
<div></div> Matthews Quality Construction				
Code: ZZ_175				
Category: Millwork	Location: Dining Room	Description: Weather strip at dining room patio door needs to be fixxed	Incomplete	
Partner: Matthews Quality Construction	Type:			
<div></div> Tile Interiors				
Code: ZZ_171				
Category: Tile	Location: Bathroom 1	Description: Told touch-up throughout Grout touch up at wall transition in master shower next to bull nose	Incomplete	
Partner: Tile Interiors	Type: Grout cracked/missing			
Code: ZZ_180				
Category: Tile	Location: Laundry Room	Description: Grout crack next to laundry cabinets	Incomplete	
Partner: Tile Interiors	Type: Grout cracked/missing			
<div></div> Tri Valley Plastering & Drywall				

Code: ZZ_181

Category: Stucco

Location: Backyard

Description: Refog stucco

Incomplete

Partner: Tri Valley
Plastering & Drywall

Type: Dash blotchy