De Young Properties

| Lot 530/Tract 0273 | Items: 25 | CH Items: 8 | Checklist Inspections: 0 |
|--|---|--|-----------------------------|
| Cabinet Connection | | | |
| Code: ZZ_1371 Category: Cabinets Partner: Cabinet Connection | Location: Kitchen Type: Cabinet missing trim or other parts | Description: Missing Twe | Incomplete |
| Code: ZZ_1372 Category: Cabinets Partner: Cabinet Connection | Location: Kitchen Type: Cabinet missing trim or other parts | Description: Missing knobs above fridge surround | Incomplete |
| Code: ZZ_1373 Category: Cabinets Partner: Cabinet Connection | Location: Kitchen Type: Cabinet missing trim or other parts | Description: Missing knobs right of oven | Incomplete |
| Code: ZZ_1374 Category: Cabinets Partner: Cabinet Connection | Location: Kitchen Type: Cabinet missing trim or other parts | Description: Missing knobs left of oven | Incomplete |
| Code: ZZ_1375 Category: Cabinets Partner: Cabinet Connection | Location: Kitchen Type: Cabinet missing trim or other parts | Description: Missing knobs on island | Incomplete |
| Code: ZZ_1376 Category: Cabinets Partner: Cabinet Connection | Location: Kitchen Type: Cabinet missing trim or other parts | Description: Missing knobs on all uppers | Incomplete |
| Code: ZZ_1385 Category: Cabinets Partner: Cabinet Connection | Location: Bathroom 1 Type: Cabinet missing trim or other parts | Description: Missing Twe | Incomplete |

| Lot 530/Tract 0273 | Items: 25 | CH Items: 8 | Checklist Inspections: 0 |
|--|--|--|-----------------------------|
| Code: ZZ_1388 Category: Cabinets Partner: Cabinet Connection | Location: Bathroom 2 Type: Cabinet missing trim or other parts | Description: Missing twe | Incomplete |
| Central Distributing | | | |
| Code: ZZ_1384 Category: Fireplace Unit Partner: Central Distributing | Location: Great Room Type: Missing parts or all parts not installed | Description: Finish start up | Incomplete |
| Donald P. Dick | | | |
| Code: ZZ_1391 Category: HVAC Partner: Donald P. Dick | Location: Bathroom 2 Type: Exhaust fan is not balanced - too loud | Description: Missing exhaust fan cover | Incomplete |
| Ferguson | | | |
| Code: ZZ_1377 Category: Appliances Partner: Ferguson | Location: Kitchen Type: Appliance(s) missing | Description: Missing oven | CRITICAL Incomplete |
| Code: ZZ_1378 Category: Appliances Partner: Ferguson | Location: Kitchen Type: Appliance(s) missing | Description: Missing stovetop | CRITICAL Incomplete |
| Code: ZZ_1379 Category: Appliances Partner: Ferguson | Location: Kitchen Type: Appliance(s) missing | Description: Missing microwave | CRITICAL Incomplete |
| Code: ZZ_1380 Category: Appliances Partner: Ferguson | Location: Kitchen Type: Appliance(s) missing | Description: Missing dishwasher | CRITICAL Incomplete |
| Code: ZZ_1381 Category: Appliances Partner: Ferguson | Location: Kitchen Type: Appliance(s) missing | Description: Missing hood chase | CRITICAL Incomplete |

Checklist Lot 530/Tract 0273 Items: 25 CH Items: 8 Inspections: 0 Code: ZZ_1394 Location: Bedroom 2 Category: Electrical Description: Missing light Incomplete Type: Light fixture, or pieces of Partner: MV Style Electric light fixture, are missing **Quality Plumbing** Code: ZZ_1386 Location: Bathroom 1 Category: Plumbing Description: Missing CRITICAL Type: Missing faucet, shower Incomplete faucets Partner: Quality Plumbing head, handle, etc Code: ZZ_1389 Location: Bathroom 2 Category: Plumbing Description: Missing Type: Missing faucet, shower faucet Incomplete Partner: Quality Plumbing head, handle, etc