

All Defects		Lot 16/Tract 6164		
<div><div></div>Anlin Windows</div>				
Code: ZZ_1582		Location:	Description: Install screens and slide and glide all windows in home	Incomplete
Category: Windows		Type:		
Partner: Anlin Windows				
<div><div></div>Cabinet Connection</div>				
Code: ZZ_1595		Location:	Description: Cabinet scratches in kitchen	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_1599		Location:	Description: Cabinet scratches in master bath and replace bottom board in left vanity dented	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
<div><div></div>Donald P. Dick</div>				
Code: ZZ_1583		Location:	Description: Start up hvac	Incomplete
Category: HVAC		Type:		
Partner: Donald P. Dick				
Code: ZZ_1584		Location:	Description: Complete hood in kitchen	Incomplete
Category: HVAC		Type:		
Partner: Donald P. Dick				
<div><div></div>Elia Painting</div>				
Code: ZZ_1581		Location:	Description: Front and back door need to be painted	Incomplete
Category: Paint		Type:		
Partner: Elia Painting				
Code: ZZ_1585		Location:	Description: Corners of door casing in bed 3	Incomplete
Category: Paint		Type:		
Partner: Elia Painting				

All Defects

Lot 16/Tract 6164

Code: ZZ_1586	Location:		
Category: Paint	Type:	Description: Crack in corner of entry	Incomplete
Partner: Elia Painting			
Code: ZZ_1587	Location:		
Category: Paint	Type:	Description: Paint in entry and bullnose	Incomplete
Partner: Elia Painting			
Code: ZZ_1588	Location:		
Category: Paint	Type:	Description: Paint in bed 3 above closet	Incomplete
Partner: Elia Painting			
Code: ZZ_1589	Location:		
Category: Paint	Type:	Description: Paint around tub enclosure in bath 2	Incomplete
Partner: Elia Painting			
Code: ZZ_1591	Location:		
Category: Paint	Type:	Description: Paint trim and bullnose by laundry	Incomplete
Partner: Elia Painting			
Code: ZZ_1592	Location:		
Category: Paint	Type:	Description: Drywall and paint in hall under windows by courtyard	Incomplete
Partner: Elia Painting			
Code: ZZ_1593	Location:		
Category: Paint	Type:	Description: Paint touch up in dining room	Incomplete
Partner: Elia Painting			
Code: ZZ_1596	Location:		
Category: Paint	Type:	Description: Paint in great room	Incomplete
Partner: Elia Painting			
Code: ZZ_1597	Location:		
Category: Paint	Type:	Description: Paint locations marked in den	Incomplete
Partner: Elia Painting			

Code: ZZ\_1598

Category: Paint

Partner: Elia Painting

Location:

Type:

Description: Paint in master bedroom

Incomplete

Ideal Custom Tile

Code: ZZ\_1590

Category: Tile

Partner: Ideal Custom Tile

Location:

Type:

Description: Grout crack in bath 2 by tub

Incomplete

Ohanians Drywall

Code: ZZ\_1594

Category: Drywall

Partner: Ohanians Drywall

Location:

Type:

Description: Finish drywall by outlet in dining room

Incomplete

Code: ZZ\_1601

Category: Drywall

Partner: Ohanians Drywall

Location:

Type:

Description: Repair drywall in master bathroom water closet where hole Was cut

Incomplete

Simas Flooring & Design

Code: ZZ\_1600

Category: Carpet / Hardwood / Laminate

Partner: Simas Flooring & Design

Location:

Type:

Description: Install carpet in master closet

Incomplete

Tri Valley Plastering & Drywall

Code: ZZ\_1602

Category: Stucco

Partner: Tri Valley Plastering & Drywall

Location:

Type:

Description: Repair stucco on right side of garage

Incomplete

Code: ZZ\_1603

Category: Stucco

Partner: Tri Valley Plastering & Drywall

Location:

Type:

Description: Remove excess stucco by Linkus box

Incomplete