De Young Properties

All Defects	Lot 16/Tract 6101		
Anlin Windows			
Code: ZZ_3171 Category: Windows Partner: Anlin Windows	Location: Kitchen Type:	Description: Screen at kitchen window is ripped	Incomplete
De Young Propertie	s		
Code: ZZ_3169 Category: Electrical Partner: De Young Properties	Location: Bathroom 3 Type:	Description: Missing bulbs at bath 3 vanity	Incomplete
Elia Painting			
Code: ZZ_3168 Category: Paint Partner: Elia Painting	Location: Bathroom 3 Type:	Description: Paint touch up front door around hardware and inside the front door and trim Den/bedroom 4 touch up baseboards and door trim	Incomplete
Code: ZZ_3170 Category: Paint Partner: Elia Painting	Location: Entryway Type:	Description: Paint touch up needed next to door to Sales office on wall	Incomplete
Code: ZZ_3172 Category: Paint Partner: Elia Painting	Location: Great Room Type:	Description: Paint touch up needed at baseboards around dining and kitchen Touch up at wall in great room	Incomplete
Code: ZZ_3173 Category: Paint Partner: Elia Painting	Location: Stairwell Type:	Description: Paint touch up needed at baseboards in stairwell	Incomplete
Code: ZZ_3174 Category: Paint Partner: Elia Painting	Location: Bedroom 1 Type:	Description: Paint touch up needed at base and door trim around home	Incomplete

All Defects	Lot 16/Tract 6101		
Code: ZZ_3175 Category: Paint Partner: Elia Painting	Location: Bathroom 1 Type:	Description: Crown molding paint touch up in master bath water closet	Incomplete
Code: ZZ_3175 Category: Paint Partner: Elia Painting	Location: Bathroom 1 Type:	Description: Crown molding paint touch up in master bath water closet And in master closet crown And in master bedroom crown Bull noses need touch up	Incomplete
Code: ZZ_3176 Category: Paint Partner: Elia Painting	Location: Laundry Room Type:	Description: Bed 2 bullnose paint touch up Wall between bed 2 and 3 need touch up Bed 3 wall Bullnose by master In laundry room	Incomplete