





All Defects		Lot 25/Tract 6164		
<div><div></div>Cabinet Connection</div>				
Code: ZZ_2415		Location:	Description: Crown missing in kitchen	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
<div><div></div>Elia Painting</div>				
Code: ZZ_2401		Location:	Description: Paint touch up master bedroom	Incomplete
Category: Paint		Type:		
Partner: Elia Painting				
Code: ZZ_2417		Location:	Description: Paint facia on front of house	Incomplete
Category: Paint		Type:		
Partner: Elia Painting				
<div><div></div>Fresno Shower Door & Mirror</div>				
Code: ZZ_2398		Location:	Description: Missing shower enclosure in master	Incomplete
Category: Shower Door & Mirror		Type:		
Partner: Fresno Shower Door & Mirror				
Code: ZZ_2399		Location:	Description: Missing mirrors in master bath	Incomplete
Category: Shower Door & Mirror		Type:		
Partner: Fresno Shower Door & Mirror				
Code: ZZ_2403		Location:	Description: Missing shower enclosure in bath 2	Incomplete
Category: Shower Door & Mirror		Type:		
Partner: Fresno Shower Door & Mirror				

Code: ZZ_2404			
Category: Shower Door & Mirror	Location:	Description: Missing mirror in bath 2	Incomplete
Partner: Fresno Shower Door & Mirror	Type:		
Code: ZZ_2408			
Category: Shower Door & Mirror	Location:	Description: Missing mirrors in bath 3	Incomplete
Partner: Fresno Shower Door & Mirror	Type:		
Code: ZZ_2412			
Category: Shower Door & Mirror	Location:	Description: Missing mirror in powder bath	Incomplete
Partner: Fresno Shower Door & Mirror	Type:		
 Ideal Custom Tile			
Code: ZZ_2407			
Category: Tile	Location:	Description: Grout crack by tub in bath 3	Incomplete
Partner: Ideal Custom Tile	Type:		
 Ohanians Drywall			
Code: ZZ_2400			
Category: Drywall	Location:	Description: Drywall crack in ceiling of master bedroom	Incomplete
Partner: Ohanians Drywall	Type:		
Code: ZZ_2406			
Category: Drywall	Location:	Description: Drywall in bath 3	Incomplete
Partner: Ohanians Drywall	Type:		
Code: ZZ_2409			
Category: Drywall	Location:	Description: 2 drywall lines in stairwell	Incomplete
Partner: Ohanians Drywall	Type:		
Code: ZZ_2410			
Category: Drywall	Location:	Description: Drywall line in den ceiling	Incomplete
Partner: Ohanians Drywall	Type:		

Code: ZZ_2413	Location:		
Category: Drywall	Type:	Description: Drywall patch in kitchen	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_2414	Location:		
Category: Drywall	Type:	Description: Drywall in great room by speaker and by can light	Incomplete
Partner: Ohanians Drywall			
 True Frame			
Code: ZZ_2402	Location:		
Category: Framing	Type:	Description: Now in wall in bed 2	Incomplete
Partner: True Frame			
Code: ZZ_2405	Location:		
Category: Framing	Type:	Description: Now in wall by veil in bed 3	Incomplete
Partner: True Frame			
 Westech			
Code: ZZ_2411	Location:		
Category: Electrical	Type:	Description: Missing light in powder bath	Incomplete
Partner: Westech			
Code: ZZ_2416	Location:		
Category: Electrical	Type:	Description: Finish electrical in kitchen	Incomplete
Partner: Westech			