

All Defects		Lot 2/Tract 6100		
<div><div></div>Anlin Windows</div>				
Code: ZZ_3574		Location:	Description: Adjust both windows in den are difficult to open	Incomplete
Category: Windows		Type:		
Partner: Anlin Windows				
<div><div></div>Cabinet Connection</div>				
Code: ZZ_3567		Location:	Description: Right vanity in master bathroom has scratches on drawer faces	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_3569		Location:	Description: Center cabinet in master bath has scratches on top cabinet and on door corners	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_3570		Location:	Description: Chip on drawer on left vanity in master bathroom Scratches on faces of cabinets on left vanity	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_3594		Location:	Description: Scratches on cabinet door faces in laundry room Chip on false front of laundry cabinet	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_3595		Location:	Description: Deep scratch on inside of cabinet in bath 2	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_3596		Location:	Description: Scratches on face of cabinet in bath 2	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_3600		Location:	Description: Cabinet you up around fridge surround	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				

Code: ZZ_3601			
Category: Cabinets	Location:	Description: Scratches on right door under stovetop	Incomplete
Partner: Cabinet Connection	Type:		
Code: ZZ_3602			
Category: Cabinets	Location:	Description: Knot on face of microwave surround uneven stain	Incomplete
Partner: Cabinet Connection	Type:		
Code: ZZ_3603			
Category: Cabinets	Location:	Description: Scratch on false front on island	Incomplete
Partner: Cabinet Connection	Type:		
Code: ZZ_3604			
Category: Cabinets	Location:	Description: Re attach cabinet door on right side of island	Incomplete
Partner: Cabinet Connection	Type:		
<div></div> California Building Products			
Code: ZZ_3576			
Category: Fireplace Unit	Location:	Description: Finish start up of fire place	Incomplete
Partner: California Building Products	Type:		
<div></div> Central Valley Overhead Door			
Code: ZZ_3588			
Category: Garage Door	Location:	Description: Garage door opener’s on site	Incomplete
Partner: Central Valley Overhead Door	Type:		
<div></div> De Young Properties			
Code: ZZ_3571			
Category: Paint	Location:	Description: Paint drywall by master bed window	Incomplete
Partner: De Young Properties	Type:		

All Defects

Lot 2/Tract 6100

Code: ZZ_3572	Location:	Description: Paint wave by baseboard in master bathroom	Incomplete
Category: Paint	Type:		
Partner: De Young Properties			
Code: ZZ_3573	Location:	Description: Paint corners of baseboard in master bed and bullnose	Incomplete
Category: Paint	Type:		
Partner: De Young Properties			
Code: ZZ_3575	Location:	Description: Clean paint and scratches of fireplace surround	Incomplete
Category: Fireplace Surround	Type:		
Partner: De Young Properties			
Code: ZZ_3577	Location:	Description: Paint baseboard seams and corners in great room	Incomplete
Category: Paint	Type:		
Partner: De Young Properties			
Code: ZZ_3580	Location:	Description: Ding on trim around back door and cracking in corner	Incomplete
Category: Paint	Type:		
Partner: De Young Properties			
Code: ZZ_3581	Location:	Description: Paint around window in dining nook	Incomplete
Category: Paint	Type:		
Partner: De Young Properties			
Code: ZZ_3585	Location:	Description: Paint by windows in dining room	Incomplete
Category: Paint	Type:		
Partner: De Young Properties			
Code: ZZ_3586	Location:	Description: Paint bullnose by dining room	Incomplete
Category: Paint	Type:		
Partner: De Young Properties			
Code: ZZ_3587	Location:	Description: Clean garage	Incomplete
Category: Builder Personnel	Type:		
Partner: De Young Properties			

Code: ZZ_3589	Location:		
Category: Paint	Type:	Description: Paint baseboard in bed 2	Incomplete
Partner: De Young Properties			
Code: ZZ_3592	Location:		
Category: Builder Personnel	Type:	Description: Remove numbers off of all door hinges	Incomplete
Partner: De Young Properties			
Code: ZZ_3607	Location:		
Category: Builder Personnel	Type:	Description: Clean up back patio	Incomplete
Partner: De Young Properties			
Code: ZZ_3608	Location:		
Category: Builder Personnel	Type:	Description: Install gas meter	Incomplete
Partner: De Young Properties			
<div><div></div>Donald P. Dick</div>			
Code: ZZ_3582	Location:		
Category: HVAC	Type:	Description: Start up hvac	Incomplete
Partner: Donald P. Dick			
<div><div></div>Elia Painting</div>			
Code: ZZ_3568	Location:		
Category: Paint	Type:	Description: Paint touch up in master water closet	Incomplete
Partner: Elia Painting			
Code: ZZ_3578	Location:		
Category: Paint	Type:	Description: Paint all windo sills	Incomplete
Partner: Elia Painting			
Code: ZZ_3583	Location:		
Category: Paint	Type:	Description: Paint drywall repairs in hall by courtyard	Incomplete
Partner: Elia Painting			

Code: ZZ_3590	Location:	Description: Grey paint drips on closet doors in bed 2	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_3591	Location:	Description: Paint drip on outlet in bed 3	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_3593	Location:	Description: Paint door casing to laundry room	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_3598	Location:	Description: Paint baseboard down hallway	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_3599	Location:	Description: Paint baseboard in kitchen not painted	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_3606	Location:	Description: Paint touch up backside of front door	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
<div></div> Fenceworks			
Code: ZZ_3609	Location:	Description: Install fence	Incomplete
Category: Fence	Type:		
Partner: Fenceworks			
<div></div> Ferguson			
Code: ZZ_3579	Location:	Description: Install appliances in kitchen	Incomplete
Category: Appliances	Type:		
Partner: Ferguson			
<div></div> Granite Mountain Stone Design			

All Defects		Lot 2/Tract 6100		
Code: ZZ_3605				
Category: Solid Surface		Location:	Description: Rust on edge of island	Incomplete
Partner: Granite Mountain Stone Design		Type:		
<div><div></div> Ideal Custom Tile</div>				
Code: ZZ_3597				
Category: Tile		Location:	Description: Excess grout on tile in bath 2	Incomplete
Partner: Ideal Custom Tile		Type:		
<div><div></div> Ohanians Drywall</div>				
Code: ZZ_3584				
Category: Drywall		Location:	Description: Drywall really flat in between dining room windows	Incomplete
Partner: Ohanians Drywall		Type:		