

All Defects

Lot 15/Tract 6101

Elia Painting

Code: ZZ_3161	Location: Front Porch	Description: Front door needs touch up around lock and handle	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_3161	Location: Front Porch	Description: Front door needs touch up around lock and handle Inside the door - shell white And in entry way wall has two different products Repaint entryway	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_3162	Location: Bedroom 2	Description: Paint touch up needed in bed 2 - by entry door and door trim And by stage Baseboards need touch up too	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_3164	Location: Bathroom 1	Description: Paint touch up needed in dining room Touch up needed in den Bullnose to master Wall in master by door is different products Also bull nose to master bath	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_3166	Location: Bathroom 1	Description: Caulking touch up in master by sink needs to be cleaned up	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			

Tile Interiors

Code: ZZ_3165	Location: Bathroom 1	Description: Tile at master shower has grout cracked Cracked tile under middle vanity	Incomplete
Category: Tile	Type:		
Partner: Tile Interiors			

Tri Valley Plastering & Drywall

Code: ZZ_3167	Location: Exterior	Description: Touch up stucco under thresholds in patio and courtyard areas	Incomplete
Category: Stucco	Type:		
Partner: Tri Valley Plastering & Drywall			

Westech

Code: ZZ_3163	Location: Laundry Room		
Category: Electrical		Description: Light in laundry room is not turning on	Incomplete
Partner: Westech	Type:		

Code: ZZ_3163	Location: Laundry Room		
Category: Electrical		Description: Light in laundry room is not turning on	Incomplete
Partner: Westech	Type:		