

| | | | |
|------------------|----------|-------------|-----------------------------|
| Lot 1/Tract 1812 | Items: 5 | CH Items: 2 | Checklist Inspections: 0 |
|------------------|----------|-------------|-----------------------------|

Central Valley Rain Gutters

| | | | |
|--------------------------------------|-------------------------------------|--|----------|
| Code: ZZ_092 | Location: Backyard | Description: Gutter down spout by patio - there's a drain but no down spout | Complete |
| Category: Rain Gutters | Type: Not connected to drain system | | |
| Partner: Central Valley Rain Gutters | | | |
| Code: ZZ_093 | Location: Backyard | Description: Other gutter downspout spout is not connected to drain by patio | Complete |
| Category: Rain Gutters | Type: Not connected to drain system | | |
| Partner: Central Valley Rain Gutters | | | |
| Code: ZZ_097 | Location: Backyard | Description: Gutter down spout missing in side yard | Complete |
| Category: Rain Gutters | Type: Not connected to drain system | | |
| Partner: Central Valley Rain Gutters | | | |

Landscape Connection

| | | | |
|-------------------------------|--|--|----------------------|
| Code: ZZ_095 | Location: Backyard | Description: Gutter downspout by man - door is not connected to drain vent | CRITICAL Complete |
| Category: Landscaping | Type: Man door gutter downspout not connected to drain | | |
| Partner: Landscape Connection | | | |

Tri Valley Plastering & Drywall

| | | | |
|--|---|--|----------------------|
| Code: ZZ_094 | Location: Backyard | Description: Remove stucco from bathroom drain clean out | CRITICAL Complete |
| Category: Stucco | Type: Stucco over the drain needs to be removed | | |
| Partner: Tri Valley Plastering & Drywall | | | |