De Young Properties

Lot 2/Tract 6349	Items: 20	CH Items: 2	Checklist Inspections: 213
Cabinet Connection	on		
Code: ZZ_1014 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 2 Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on door under sink	Incomplete
Code: ZZ_1015 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 2 Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratch on door left of sink	Incomplete
Code: ZZ_1020 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratch on right vanity door	Incomplete
Code: ZZ_1021 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Blemish on drawer right of sink	Incomplete
Code: ZZ_1022 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on false front under sink	Incomplete
Code: ZZ_1023 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Avon side of microwave surround	Incomplete
Code: ZZ_1024 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Crown left of hood damaged	Incomplete

Lot 2/Tract 6349	Items: 20	CH Items: 2	Checklist Inspections: 213
Code: ZZ_1025 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Lower corner cabinet scratches	Incomplete
Code: ZZ_1026 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on fridge surround	Incomplete
Code: ZZ_1027 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on right side pantry doors	Incomplete
Elia Painting			
Code: ZZ_1016 Category: Paint Partner: Elia Painting	Location: Entryway Type: Touch-up required	Description: Paint touch up by door casing to laundry room	Incomplete
Code: ZZ_1018 Category: Paint Partner: Elia Painting	Location: Bedroom 1 Type: Touch-up required	Description: Touch up by baseboard under window	Incomplete
Fenceworks			
Code: ZZ_1032 Category: Fence Partner: Fenceworks	Location: Exterior Type: Warped	Description: Missing back fence side	Incomplete
Ferguson			
Code: ZZ_1028 Category: Appliances Partner: Ferguson	Location: Kitchen Type: Appliance(s) missing	Description: Not installed yet	CRITICAL Incomplete

Code: ZZ_1030

Category: Concrete

Location: Exterior

Partner: G&G Concrete

Type: Cracks/gouges/chips

Description: Walkway to man door forms are

set

Incomplete



Landscape Connection

Code: ZZ_1029

Category: Landscaping Location: Exterior

Type: Missing

Description: Not installed yet

CRITICAL Incomplete

Partner: Landscape

Connection



Code: ZZ_1013

Category: Drywall

Partner: Ohanians

Drywall

Location: Entryway

Type: Drywall has crack, gash, hole,

and/or gouge

Description: Nail pops

above front door

Incomplete

Code: ZZ 1019

Category: Drywall

Partner: Ohanians

Drywall

Location: Bathroom 1

Type: Drywall texture issues

Description: Drywall

gap by window by

bathtub

Incomplete



Premier Door

Code: ZZ_1017

Category: Millwork

Partner: Premier

Door

Location: Great Room

Type: Baseboards missing or have

chips/gouges

Description: Gash on baseboard in great

room

Incomplete



Tri Valley Plastering & Drywall

Code: ZZ_1031

Category: Stucco Location: Exterior

Partner: Tri Valley Plastering & Drywall Type: Chip/crack/gouge

Description: Chips in

stucco by gate

Incomplete