


Lot 10/Tract 6100		Items: 36	CH Items: 0	Checklist Inspections: 0
<div><div></div>Anlin Windows</div>				
Code: J_053				
Category: Windows	Location: Bedroom 4	Description: Remove red adhesive off window frame	Incomplete	
Partner: Anlin Windows	Type: Window glass has scratches			
<div><div></div>Cabinet Connection</div>				
Code: B_075				
Category: Cabinets	Location: Bathroom 2	Description: Scratches on door fronts	Incomplete	
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets			
Code: B_076				
Category: Cabinets	Location: Bathroom 3	Description: Scratches on Twe	Incomplete	
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets			
Code: B_077				
Category: Cabinets	Location: Kitchen	Description: Scratches on side of oven surround	Incomplete	
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks			
Code: B_078				
Category: Cabinets	Location: Kitchen	Description: Scratches on door front under stovetop	Incomplete	
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks			
Code: B_079				
Category: Cabinets	Location: Kitchen	Description: Scratches on pantry cabinet	Incomplete	
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks			

Lot 10/Tract 6100		Items: 36	CH Items: 0	Checklist Inspections: 0
Code: B_080				
Category: Cabinets	Location: Kitchen		Description: Scratches on top panel of drop zone cabinets	Incomplete
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks			
 Elia Painting				
Code: A_086				
Category: Paint	Location: Flex Den		Description: Paint touch up by corner of wall in bonus room	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: A_087				
Category: Paint	Location: Flex Den		Description: Remove excess paint from French doors	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: A_088				
Category: Paint	Location: Dining Room		Description: Touch up paint around slider	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: A_089				
Category: Paint	Location: Great Room		Description: Touch up around window in great room	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: A_090				
Category: Paint	Location: Great Room		Description: Touch up on media wall	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: A_091				
Category: Paint	Location: Great Room		Description: Touch up by thermostat	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: A_092				
Category: Paint	Location: Great Room		Description: Finish painting base	Incomplete
Partner: Elia Painting	Type: Touch-up required			

Lot 10/Tract 6100		Items: 36	CH Items: 0	Checklist Inspections: 0
Code: A_093				
Category: Paint	Location: Bedroom 4		Description: Touch up under window in bed 4	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: A_094				
Category: Paint	Location: Bedroom 4		Description: Touch up on wall left of door	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: A_095				
Category: Paint	Location: Bathroom 3		Description: Touch up on wall left of window	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: A_096				
Category: Paint	Location: Bathroom 3		Description: Touch up on wall opposit of closet	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: A_097				
Category: Paint	Location: Bathroom 3		Description: Paint baseboard	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: A_098				
Category: Paint	Location: Laundry Room		Description: Paint and caulk baseboard	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: A_099				
Category: Paint	Location: Bedroom 2		Description: Paint window sill	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: A_100				
Category: Paint	Location: Bedroom 2		Description: Paint baseboard	Incomplete
Partner: Elia Painting	Type: Touch-up required			

Lot 10/Tract 6100		Items: 36	CH Items: 0	Checklist Inspections: 0
Code: A_101				
Category: Paint	Location: Bedroom 1		Description: Paint baseboard	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: A_102				
Category: Paint	Location: Bedroom 1		Description: Paint marks on wall where coax is located	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: A_103				
Category: Paint	Location: Bathroom 1		Description: Paint baseboard in master bath	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: A_104				
Category: Paint	Location: Bathroom 2		Description: Paint baseboard	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: A_105				
Category: Paint	Location: Hallway		Description: Paint banister	Incomplete
Partner: Elia Painting	Type: Touch up			
Code: A_106				
Category: Paint	Location: Stairwell		Description: Paint base	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: A_107				
Category: Paint	Location: Stairwell		Description: Paint marks in stairwell	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: A_108				
Category: Paint	Location: Bathroom 3		Description: Touch up by vanity light	Incomplete
Partner: Elia Painting	Type: Touch-up required			

Lot 10/Tract 6100		Items: 36	CH Items: 0	Checklist Inspections: 0
Code: A_109				
Category: Paint	Location: Kitchen		Description: Paint baseboard in kitchen	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: A_110				
Category: Paint	Location: Kitchen		Description: Paint wall to the right of fridge	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: A_111				
Category: Paint	Location: Exterior		Description: Paint front pop out	Incomplete
Partner: Elia Painting	Type: Stucco pop-out, shutters and/or deco vents, or fascia paint issues			
<div><div></div> Ideal Custom Tile</div>				
Code: E_016				
Category: Tile	Location: Laundry Room		Description: Fill grout by dryer vent	Incomplete
Partner: Ideal Custom Tile	Type: Grout at tile is cracked, missing, wrong color, and/or needs touch-up			
<div><div></div> Ohanians Drywall</div>				
Code: C_069				
Category: Drywall	Location: Stairwell		Description: Dent in drywall	Incomplete
Partner: Ohanians Drywall	Type: Drywall has crack, gash, hole, and/or gouge			
<div><div></div> Tri Valley Plastering &amp; Drywall</div>				
Code: F_013				
Category: Stucco	Location: Exterior		Description: Please fog match exterior of home	Incomplete
Partner: Tri Valley Plastering & Drywall	Type: Inconsistent Fog coat			