




All Defects		Lot 141/Tract 0273		
<div><div></div>Anlin Windows</div>				
Code: ZZ_4178		Location:		
Category: Windows		Type:	Description: Missing screens on all windows	Incomplete
Partner: Anlin Windows				
Code: ZZ_4196		Location:		
Category: Windows		Type:	Description: Cracked window pane in master bedroom	Incomplete
Partner: Anlin Windows				
<div><div></div>Cabinet Connection</div>				
Code: ZZ_4183		Location:		
Category: Cabinets		Type:	Description: Bath 2 Cabinet scratches on front left door face Cabinet scratches on inspect panel	Incomplete
Partner: Cabinet Connection				
Code: ZZ_4188		Location:		
Category: Cabinets		Type:	Description: Cabinet scratches above and around fridge surround on faces of doors and trim	Incomplete
Partner: Cabinet Connection				
Code: ZZ_4189		Location:		
Category: Cabinets		Type:	Description: Scratches on faces of uppers and lowers in kitchen to the right of oven	Incomplete
Partner: Cabinet Connection				
Code: ZZ_4190		Location:		
Category: Cabinets		Type:	Description: Cabinet scratches above microwave and hood box not installed	Incomplete
Partner: Cabinet Connection				
Code: ZZ_4191		Location:		
Category: Cabinets		Type:	Description: Scratches on uppers and lowers on faces of doors and drawers to the left of oven	Incomplete
Partner: Cabinet Connection				
Code: ZZ_4192		Location:		
Category: Cabinets		Type:	Description: Missing cabinet door under kitchen sink	Incomplete
Partner: Cabinet Connection				

Code: ZZ_4193			
Category: Cabinets	Location:	Description: Scratches on cabinet faces on kitchen island	Incomplete
Partner: Cabinet Connection	Type:		
Code: ZZ_4200			
Category: Cabinets	Location:	Description: Cabinet scratches on faces of doors and drawers in master bathroom	Incomplete
Partner: Cabinet Connection	Type:		
 Elia Painting			
Code: ZZ_4179			
Category: Paint	Location:	Description: Paint touch up under window in bed 3	Incomplete
Partner: Elia Painting	Type:	Caulking needed by closet door casing	
Code: ZZ_4185			
Category: Paint	Location:	Description: Paint touch up in entry by outlet	Incomplete
Partner: Elia Painting	Type:		
Code: ZZ_4195			
Category: Paint	Location:	Description: Paint touch up in great room by baseboard	Incomplete
Partner: Elia Painting	Type:		
Code: ZZ_4201			
Category: Paint	Location:	Description: Paint discoloration on master closet door	Incomplete
Partner: Elia Painting	Type:		
 Fenceworks			
Code: ZZ_4202			
Category: Fence	Location:	Description: Finish fence in backyard	Incomplete
Partner: Fenceworks	Type:		
 Fresno Shower Door & Mirror			

Code: ZZ_4182				
Category: Shower Door & Mirror	Location:		Description: Missing mirror in bath 2	Incomplete
	Type:			
Partner: Fresno Shower Door & Mirror				
Code: ZZ_4197				
Category: Shower Door & Mirror	Location:		Description: Missing mirrors in master bathroom	Incomplete
	Type:			
Partner: Fresno Shower Door & Mirror				
Code: ZZ_4199				
Category: Shower Door & Mirror	Location:		Description: Missing shower enclosure in master shower	Incomplete
	Type:			
Partner: Fresno Shower Door & Mirror				
<div><div></div>Ohanians Drywall</div>				
Code: ZZ_4180				
Category: Drywall	Location:		Description: Drywall booger left wall in bed 3	Incomplete
	Type:			
Partner: Ohanians Drywall				
Code: ZZ_4184				
Category: Drywall	Location:		Description: Drywall touch up in 2 locations in bed 2	Incomplete
	Type:			
Partner: Ohanians Drywall				
<div><div></div>Quality Plumbing</div>				
Code: ZZ_4181				
Category: Plumbing	Location:		Description: Water plugged in bath 2 tub	Incomplete
	Type:			
Partner: Quality Plumbing				
<div><div></div>Visalia Tile</div>				
Code: ZZ_4186				
Category: Tile	Location:		Description: Excess thinset on tile in hall	Incomplete
	Type:			
Partner: Visalia Tile				

All Defects		Lot 141/Tract 0273	
Code: ZZ_4187			
Category: Tile	Location:	Description: Fill grout by fridge surround	Incomplete
Partner: Visalia Tile	Type:		
Code: ZZ_4194			
Category: Tile	Location:	Description: Grout touch up by kitchen island	Incomplete
Partner: Visalia Tile	Type:		
Code: ZZ_4198			
Category: Tile	Location:	Description: Missing corner shelves in master shower	Incomplete
Partner: Visalia Tile	Type:		