



All Defects		Lot 134/Tract 0273	
	Cabinet Connection		
Code: ZZ_3971			
Category: Cabinets	Location:	Description: Cabinet touch up right side of vanity in bath 2	Incomplete
Partner: Cabinet Connection	Type:		
Code: ZZ_3989			
Category: Cabinets	Location:	Description: Cabinet touch up on corners of doors and drawers in master bathroom	Incomplete
Partner: Cabinet Connection	Type:		
Code: ZZ_3990			
Category: Cabinets	Location:	Description: Scratches on paneling on sides of island	Incomplete
Partner: Cabinet Connection	Type:		
Code: ZZ_3991			
Category: Cabinets	Location:	Description: -cabinet touch up on upper cabinets right side of oven -cabinet touch up on corners of doors and drawers on bottom cabinets to the right of oven	Incomplete
Partner: Cabinet Connection	Type:		
Code: ZZ_3995			
Category: Cabinets	Location:	Description: -cabinet touch up on bottom cabinets left of oven -replace 2 upper cabinet doors left of oven are damaged and cracked	Incomplete
Partner: Cabinet Connection	Type:		
Code: ZZ_3996			
Category: Cabinets	Location:	Description: Cabinet touch up dings around fridge surround	Incomplete
Partner: Cabinet Connection	Type:		
Code: ZZ_3997			
Category: Cabinets	Location:	Description: Cabinet you up on small cabinet left of pantry in kitchen on corners of doors	Incomplete
Partner: Cabinet Connection	Type:		
Code: ZZ_3998			
Category: Cabinets	Location:	Description: Cabinet stain fading on edges of cabinet doors and drawers on kitchen island	Incomplete
Partner: Cabinet Connection	Type:		

Code: ZZ_3999			
Category: Cabinets	Location:	Description: Finish install of hood box above microwave	Incomplete
Partner: Cabinet Connection	Type:		
<div><div></div>California Building Products</div>			
Code: ZZ_3977			
Category: Fireplace Unit	Location:	Description: Finish start up of fireplace	Incomplete
Partner: California Building Products	Type:		
Code: ZZ_3978			
Category: Fireplace Unit	Location:	Description: Scratches on front cover of fireplace	Incomplete
Partner: California Building Products	Type:		
<div><div></div>Elia Painting</div>			
Code: ZZ_3974			
Category: Paint	Location:	Description: Paint touch up in entry hall	Incomplete
Partner: Elia Painting	Type:		
Code: ZZ_3988			
Category: Paint	Location:	Description: Paint touch up in master closet	Incomplete
Partner: Elia Painting	Type:		
<div><div></div>Ferguson</div>			
Code: ZZ_3992			
Category: Appliances	Location:	Description: Finish install of appliances	Incomplete
Partner: Ferguson	Type:		
<div><div></div>John Ventresca Co</div>			
Code: ZZ_3979			
Category: Fireplace Surround	Location:	Description: Grout crack around fireplace mantle	Incomplete
Partner: John Ventresca Co	Type:		

<div><div></div>Matthews Quality Construction</div>				
Code: ZZ_3987				
Category: Millwork	Location:	Description: Missing toilet paper holder in master bathroom		Incomplete
Partner: Matthews Quality Construction	Type:			
<div><div></div>Ohanians Drywall</div>				
Code: ZZ_3975				
Category: Drywall	Location:	Description: Drywall touch up in entry hall		Incomplete
Partner: Ohanians Drywall	Type:			
Code: ZZ_3980				
Category: Drywall	Location:	Description: Drywall repair in master bedroom		Incomplete
Partner: Ohanians Drywall	Type:			
Code: ZZ_3981				
Category: Drywall	Location:	Description: Drywall repair by coax in master bedroom		Incomplete
Partner: Ohanians Drywall	Type:			
<div><div></div>Quality Plumbing</div>				
Code: ZZ_3969				
Category: Plumbing	Location:	Description: Toilet missing in bath 2		Incomplete
Partner: Quality Plumbing	Type:			
Code: ZZ_3970				
Category: Plumbing	Location:	Description: Missing faucet in bath 2		Incomplete
Partner: Quality Plumbing	Type:			
Code: ZZ_3972				
Category: Plumbing	Location:	Description: Missing shower faucet in bath 2		Incomplete
Partner: Quality Plumbing	Type:			

Code: ZZ_3976			
Category: Plumbing	Location:	Description: Missing water heater	Incomplete
Partner: Quality Plumbing	Type:		
Code: ZZ_3983			
Category: Plumbing	Location:	Description: Missing faucets in master bathroom	Incomplete
Partner: Quality Plumbing	Type:		
Code: ZZ_3984			
Category: Plumbing	Location:	Description: Missing faucet for master shower	Incomplete
Partner: Quality Plumbing	Type:		
Code: ZZ_3986			
Category: Plumbing	Location:	Description: Missing toilet in master bathroom	Incomplete
Partner: Quality Plumbing	Type:		
Code: ZZ_3993			
Category: Plumbing	Location:	Description: Faucet missing in kitchen	Incomplete
Partner: Quality Plumbing	Type:		
 Tri Valley Plastering & Drywall			
Code: ZZ_4000			
Category: Stucco	Location:	Description: Remove stucco netting on bottom left side of house	Incomplete
Partner: Tri Valley Plastering & Drywall	Type:		
 Visalia Tile			
Code: ZZ_3968			
Category: Tile	Location:	Description: Grout missing in bed 3 by closet	Incomplete
Partner: Visalia Tile	Type:		
Code: ZZ_3985			
Category: Tile	Location:	Description: Missing drain for master shower	Incomplete
Partner: Visalia Tile	Type:		

 Westech

Code: ZZ_3973	Location:	Description: Missing globes on vanity Light in bath 2	Incomplete
Category: Electrical	Type:		
Partner: Westech			
Code: ZZ_3982	Location:	Description: Missing vanity lights in master bathroom	Incomplete
Category: Electrical	Type:		
Partner: Westech			
Code: ZZ_3994	Location:	Description: Missing outlet in kitchen	Incomplete
Category: Electrical	Type:		
Partner: Westech			