De Young Properties

| All Defects | Lot 27/Trac | Lot 27/Tract 6260 | | |
|---|--------------------|---|------------|--|
| Anlin Windows | | | | |
| Code: ZZ_403 Category: Windows Partner: Anlin Windows | Location: Type: | Description: Bed 5 window has excess sticky on edge of window | Incomplete | |
| Code: ZZ_412 Category: Windows Partner: Anlin Windows | Location: Type: | Description: Window in master bath | Incomplete | |
| Code: ZZ_418 Category: Windows Partner: Anlin Windows | Location: Type: | Description: Bound room window latch | Incomplete | |
| Cabinet Connection | | | | |
| Code: ZZ_408 Category: Cabinets Partner: Cabinet Connection | Location: Type: | Description: Cabinet touch up in bath 2 | Incomplete | |
| Code: ZZ_415 Category: Cabinets Partner: Cabinet Connection | Location: Type: | Description: Cabinet touch up in master bath | Incomplete | |
| Code: ZZ_416 Category: Cabinets Partner: Cabinet Connection | Location: Type: | Description: Trim on bath 4 cabinets missing | Incomplete | |
| Code: ZZ_417 Category: Cabinets Partner: Cabinet Connection | Location: Type: | Description: Kitchen touch up | Incomplete | |
| Code: ZZ_419 Category: Cabinets Partner: Cabinet Connection | Location: Type: | Description: Kitchen cabinet missing 1/4 round on right side of microwave | Incomplete | |

| All Defects | Lot 27/Trac | Lot 27/Tract 6260 | | | |
|--|--------------------|--|------------|--|--|
| Everlast Paint | | | | | |
| Code: ZZ_402 Category: Paint Partner: Everlast Paint | Location: Type: | Description: Door has rough edge in upstairs hall | Incomplete | | |
| Code: ZZ_405 Category: Paint Partner: Everlast Paint | Location: Type: | Description: Bath 3 pain transition is a different color | Incomplete | | |
| Code: ZZ_406 Category: Paint Partner: Everlast Paint | Location: Type: | Description: Door to closet in bed 4 paint is peeling | Incomplete | | |
| Code: ZZ_410 Category: Paint Partner: Everlast Paint | Location: Type: | Description: Caulk baseboard in bath 2 water closet | Incomplete | | |
| Code: ZZ_411 Category: Paint Partner: Everlast Paint | Location: Type: | Description: Paint trim bed 2 | Incomplete | | |
| Ohanians Drywall | | | | | |
| Code: ZZ_407 Category: Drywall Partner: Ohanians Drywall | Location: Type: | Description: Drywall hole behind bed 3 door | Incomplete | | |
| Premier Door | | | | | |
| Code: ZZ_401 Category: Millwork Partner: Premier Door | Location: Type: | Description: Baseboard upstairs hall has diviots | Incomplete | | |
| Quality Plumbing | | | | | |

| All Defects | Lot 27/Tract 6260 | | | |
|---|--------------------|--|------------|--|
| Code: ZZ_414 Category: Plumbing Partner: Quality Plumbing | Location: Type: | Description: Caulking around master tub and where is the access panel for jetted tub | Incomplete | |
| Tile Interiors | | | | |
| Code: ZZ_404 Category: Tile Partner: Tile Interiors | Location: Type: | Description: Grout needed by corner of bath 3 by tub | Incomplete | |
| Code: ZZ_409 Category: Tile Partner: Tile Interiors | Location: Type: | Description: Finish tile shower in bath 2 and correct grout line | Incomplete | |
| Code: ZZ_413 Category: Tile Partner: Tile Interiors | Location: Type: | Description: Tile corners in master tub | Incomplete | |