

| All Defects | | Lot 45/Tract 6164 | | |
|--|-----------|---|------------|--|
| <div><div></div>Anlin Windows</div> | | | | |
| Code: ZZ_2889 | Location: | Description: Missing screen in dining nook | Incomplete | |
| Category: Windows | Type: | | | |
| Partner: Anlin Windows | | | | |
| Code: ZZ_2901 | Location: | Description: Missing screen in master bed | Incomplete | |
| Category: Windows | Type: | | | |
| Partner: Anlin Windows | | | | |
| Code: ZZ_2910 | Location: | Description: Missing screen in bed 4 | Incomplete | |
| Category: Windows | Type: | | | |
| Partner: Anlin Windows | | | | |
| <div><div></div>Cabinet Connection</div> | | | | |
| Code: ZZ_2886 | Location: | Description: Cabinet touch up in butlers pantry | Incomplete | |
| Category: Cabinets | Type: | | | |
| Partner: Cabinet Connection | | | | |
| Code: ZZ_2887 | Location: | Description: Crown missing in kitchen | Incomplete | |
| Category: Cabinets | Type: | | | |
| Partner: Cabinet Connection | | | | |
| Code: ZZ_2888 | Location: | Description: Cabinet touch up in kitchen | Incomplete | |
| Category: Cabinets | Type: | | | |
| Partner: Cabinet Connection | | | | |
| Code: ZZ_2894 | Location: | Description: Cabinet touch up in laundry room | Incomplete | |
| Category: Cabinets | Type: | | | |
| Partner: Cabinet Connection | | | | |
| Code: ZZ_2898 | Location: | Description: Cabinet touch up in bath 2 | Incomplete | |
| Category: Cabinets | Type: | | | |
| Partner: Cabinet Connection | | | | |

| | | | |
|--|-----------|--|------------|
| Code: ZZ_2902 | Location: | | |
| Category: Cabinets | Type: | Description: Cabinet touch up in master bath | Incomplete |
| Partner: Cabinet Connection | | | |
| Code: ZZ_2903 | Location: | | |
| Category: Cabinets | Type: | Description: Adjust cabinets in master bath | Incomplete |
| Partner: Cabinet Connection | | | |
| Code: ZZ_2906 | Location: | | |
| Category: Cabinets | Type: | Description: Touch up cabinets in bath 3 | Incomplete |
| Partner: Cabinet Connection | | | |
| <div><div></div>California Building Products</div> | | | |
| Code: ZZ_2912 | Location: | | |
| Category: Fireplace Unit | Type: | Description: Deep gouge on fireplace insert | Incomplete |
| Partner: California Building Products | | | |
| Code: ZZ_2913 | Location: | | |
| Category: Fireplace Unit | Type: | Description: Start up fireplace | Incomplete |
| Partner: California Building Products | | | |
| <div><div></div>De Young Properties</div> | | | |
| Code: ZZ_2883 | Location: | | |
| Category: Builder Personnel | Type: | Description: Gash on brick wall | Incomplete |
| Partner: De Young Properties | | | |
| <div><div></div>Elia Painting</div> | | | |
| Code: ZZ_2890 | Location: | | |
| Category: Paint | Type: | Description: Paint base in bed 5 | Incomplete |
| Partner: Elia Painting | | | |
| Code: ZZ_2892 | Location: | | |
| Category: Paint | Type: | Description: Repaint base in bed 3 running paint | Incomplete |
| Partner: Elia Painting | | | |

| | | | |
|---|-----------|--|------------|
| Code: ZZ_2893 | Location: | | |
| Category: Paint | Type: | Description: Paint above closet base in bed3 | Incomplete |
| Partner: Elia Painting | | | |
| Code: ZZ_2897 | Location: | | |
| Category: Paint | Type: | Description: Paint by baseboard in bed 2 | Incomplete |
| Partner: Elia Painting | | | |
| Code: ZZ_2900 | Location: | | |
| Category: Paint | Type: | Description: Paint touch up in master bed | Incomplete |
| Partner: Elia Painting | | | |
| Code: ZZ_2911 | Location: | | |
| Category: Paint | Type: | Description: Paint touch up on baseboard in hall | Incomplete |
| Partner: Elia Painting | | | |
| <div><div></div>Matthews Quality Construction</div> | | | |
| Code: ZZ_2896 | Location: | | |
| Category: Millwork | Type: | Description: Broken baseboard in bed 2 | Incomplete |
| Partner: Matthews Quality Construction | | | |
| Code: ZZ_2899 | Location: | | |
| Category: Millwork | Type: | Description: Re install base behind toilet in bath 2 | Incomplete |
| Partner: Matthews Quality Construction | | | |
| <div><div></div>Ohanians Drywall</div> | | | |
| Code: ZZ_2885 | Location: | | |
| Category: Drywall | Type: | Description: Texture on window sill in dining room | Incomplete |
| Partner: Ohanians Drywall | | | |
| Code: ZZ_2891 | Location: | | |
| Category: Drywall | Type: | Description: Drywall touch up in ned3 | Incomplete |
| Partner: Ohanians Drywall | | | |

| | | | |
|---|-----------|--|------------|
| Code: ZZ_2895 | Location: | Description: Holes in drywall in hall by laundry room | Incomplete |
| Category: Drywall | Type: | | |
| Partner: Ohanians Drywall | | | |
| Code: ZZ_2908 | Location: | Description: Drywall repair in stairwell | Incomplete |
| Category: Drywall | Type: | | |
| Partner: Ohanians Drywall | | | |
| Code: ZZ_2909 | Location: | Description: Drywall repair on window sill in bed4 | Incomplete |
| Category: Drywall | Type: | | |
| Partner: Ohanians Drywall | | | |
| <div></div> Quality Plumbing | | | |
| Code: ZZ_2904 | Location: | Description: Scratch on toilet seat in master bath | Incomplete |
| Category: Plumbing | Type: | | |
| Partner: Quality Plumbing | | | |
| Code: ZZ_2905 | Location: | Description: Install toilet paper holder in master bath toilet | Incomplete |
| Category: Plumbing | Type: | | |
| Partner: Quality Plumbing | | | |
| Code: ZZ_2907 | Location: | Description: Install towel bar in bath 3 | Incomplete |
| Category: Plumbing | Type: | | |
| Partner: Quality Plumbing | | | |
| <div></div> Tri Valley Plastering & Drywall | | | |
| Code: ZZ_2882 | Location: | Description: Stucco repair above window | Incomplete |
| Category: Stucco | Type: | | |
| Partner: Tri Valley Plastering & Drywall | | | |
| Code: ZZ_2884 | Location: | Description: Re fog home | Incomplete |
| Category: Stucco | Type: | | |
| Partner: Tri Valley Plastering & Drywall | | | |