

All Defects		Lot 12/Tract 6102		
<div><div></div>Cabinet Connection</div>				
Code: ZZ_122				
Category: Cabinets	Location: Kitchen	Description: Various chips and scratches in kitchen cabinets	Incomplete	
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)			
Code: ZZ_123				
Category: Cabinets	Location: Bedroom 1	Description: Master closet cabinets have gaps and chis	Incomplete	
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)			
<div><div></div>Everlast Paint</div>				
Code: ZZ_124				
Category: Paint	Location: Great Room	Description: Paint touch up throughout	Incomplete	
Partner: Everlast Paint	Type: Chip/gouge/scratch			
Code: ZZ_124				
Category: Paint	Location: Great Room	Description: Paint touch up throughout	Incomplete	
Partner: Everlast Paint	Type:			