

All Defects		Lot 36/Tract 6102		
<div><div></div>De Young Properties</div>				
Code: Z_028		Location:		
Category: Builder Personnel		Type:	Description: Paint in bed 3 above closet	Incomplete
Partner: De Young Properties				
<div><div></div>Everlast Paint</div>				
Code: Z_029		Location:		
Category: Builder Personnel		Type:	Description: Paint touch up in bed 2 above closet	Incomplete
Partner: Everlast Paint				
Code: Z_030		Location:		
Category: Builder Personnel		Type:	Description: Various paint in great room	Incomplete
Partner: Everlast Paint				
<div><div></div>Tile Interiors</div>				
Code: G_010		Location:		
Category: Tile		Type:	Description: Grout by mater tub	Incomplete
Partner: Tile Interiors				
<div><div></div>Tri Valley Plastering & Drywall</div>				
Code: E_006		Location:		
Category: Stucco		Type:	Description: Stucco touch up cracks around home	Incomplete
Partner: Tri Valley Plastering & Drywall				