## **De Young Properties**

Lot 342/Tract 0273	Items: 23	CH Items: 5	Checklist Inspections: 176
Cabinet Connection			
Code: ZZ_602			
Category: Cabinets	Location: Kitchen	Description: Cabinet discoloration and chip in	
Partner: Cabinet Connection	Type: Discoloration	face of lower cabinets left of oven	Incomplete
Code: ZZ_603			
Category: Cabinets	Location: Kitchen	Description: Touch up needed on fridge	Incomplete
Partner: Cabinet Connection	Type: Discoloration	surround	Incomplete
Code: ZZ_604			
Category: Cabinets	Location: Kitchen	Description: Discoloration on upper cabinet faces	Incomplete
Partner: Cabinet Connection	Type: Discoloration	left of hood	псотресс
Code: ZZ_605		Description Cabinat	
Category: Cabinets	Location: Kitchen	Description: Cabinet scratches dings dents and miss drilled holes on	Incomplete
Partner: Cabinet Connection	Type: Discoloration	lower drawers to the right of oven	meompiete
Code: ZZ_606			
Category: Cabinets	Location: Kitchen	Description: Discoloration	Incomplete
Partner: Cabinet Connection	Type: Discoloration	on lower cabinet doors to the right of oven	Incomplete
Code: ZZ_607			
Category: Cabinets	Location: Kitchen	Description: Discoloration on lower cabinets to the	Incomplete
Partner: Cabinet Connection	Type: Discoloration	left of pantry	meomplete

Partner: Ferguson

Checklist Lot 342/Tract 0273 Items: 23 CH Items: 5 Inspections: 176 Code: ZZ\_613 Location: Bathroom 2 Category: Plumbing Description: Rust in Incomplete Type: Defect(s) in Bath/Shower bottom of tub fitter/surround Partner: Quality Plumbing Tri Valley Plastering & Drywall Code: ZZ\_617 Category: Stucco Location: Exterior Description: Stucco discoloration around Incomplete Partner: Tri Valley Type: Inconsistent Fog coat home Plastering & Drywall Visalia Tile Code: ZZ\_600 Location: Kitchen Description: Please Category: Tile address grout crack on Incomplete Type: Grout at tile is cracked, missing, backsplash Partner: Visalia Tile wrong color, and/or needs touch-up Code: ZZ 601 Location: Kitchen Category: Tile Description: Grout Incomplete Type: Grout at tile is cracked, missing, missing by island Partner: Visalia Tile wrong color, and/or needs touch-up Code: ZZ\_611 Location: Bathroom 1 Category: Tile Description: Excess grout Incomplete Type: Grout at tile is cracked, missing, on bullnose by shower Partner: Visalia Tile wrong color, and/or needs touch-up