

Lot 13/Tract 6349	Items: 18	CH Items: 0	Checklist Inspections: 186
-------------------	-----------	-------------	----------------------------------

 Cabinet Connection

Code: ZZ_810			
Category: Cabinets	Location: Kitchen		
	Type: Cabinets have scratches, chips, and/or cracks	Description: Scratch on corner door in kitchen	Incomplete
Partner: Cabinet Connection			
Code: ZZ_811			
Category: Cabinets	Location: Kitchen		
	Type: Cabinets have scratches, chips, and/or cracks	Description: Scratch on drawers to the right of stovetop	Incomplete
Partner: Cabinet Connection			
Code: ZZ_812			
Category: Cabinets	Location: Kitchen		
	Type: Cabinets have scratches, chips, and/or cracks	Description: Doors on right side of hood have scratches	Incomplete
Partner: Cabinet Connection			
Code: ZZ_813			
Category: Cabinets	Location: Kitchen		
	Type: Cabinets have scratches, chips, and/or cracks	Description: DWB face has hole drilled in wrong place	Incomplete
Partner: Cabinet Connection			
Code: ZZ_814			
Category: Cabinets	Location: Kitchen		
	Type: Cabinets have scratches, chips, and/or cracks	Description: Door face above fridge has scratches	Incomplete
Partner: Cabinet Connection			
Code: ZZ_815			
Category: Cabinets	Location: Kitchen		
	Type: Cabinets have scratches, chips, and/or cracks	Description: False front has scratches on it	Incomplete
Partner: Cabinet Connection			

Code: ZZ_816			
Category: Cabinets	Location: Bathroom 3	Description: Door faces have scratches on vanity	Incomplete
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets		
Code: ZZ_817			
Category: Cabinets	Location: Bathroom 3	Description: Drawer face has scratches	Incomplete
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets		
Code: ZZ_818			
Category: Cabinets	Location: Bathroom 1	Description: Scratches on right vanity drawer faces	Incomplete
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets		
Code: ZZ_819			
Category: Cabinets	Location: Bathroom 1	Description: Scratches on right side vanity false front	Incomplete
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets		
Code: ZZ_820			
Category: Cabinets	Location: Bathroom 1	Description: Scratch on right vanity door face	Incomplete
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets		
Code: ZZ_821			
Category: Cabinets	Location: Bathroom 1	Description: Drawer faces on left vanity scratched	Incomplete
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets		
Code: ZZ_822			
Category: Cabinets	Location: Bathroom 1	Description: Scratch on false front on left side of vanity	Incomplete
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets		

Code: ZZ_823			
Category: Cabinets	Location: Master Closet	Description: Missing handles on closet cabinet	Incomplete
Partner: Cabinet Connection	Type: Missing		
Code: ZZ_824			
Category: Cabinets	Location: Master Closet	Description: Scratches on cabinet in closet	Incomplete
Partner: Cabinet Connection	Type: Missing		
Code: ZZ_825			
Category: Cabinets	Location: Bathroom 2	Description: Scratches on right drawer on vanity	Incomplete
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets		
Code: ZZ_826			
Category: Cabinets	Location: Bathroom 2	Description: Scratch on cabinet door face	Incomplete
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets		
<div><div></div>Premier Door</div>			
Code: ZZ_827			
Category: Millwork	Location: Bedroom 2	Description: Gash in baseboard	Incomplete
Partner: Premier Door	Type: Baseboards missing or have chips/gouges		