De Young Properties

All Defects	Lot 123/Tra	ct 0273	
Cabinet Connection			
Code: ZZ_3180 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Scratches on left drawer in master bath Glue left on exterior of front cabinet in master bath.	Incomplete
Code: ZZ_3195 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Cabinet scratch on on island underneath	Incomplete
Code: ZZ_3197 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Cabinet scratch on side of cabinet island	Incomplete
Code: ZZ_3199 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Cabinet scratches on drop zone cabinet	Incomplete
Central Valley Overhead Door			
Code: ZZ_3206 Category: Garage Door Partner: Central Valley Overhead Door	Location: Type:	Description: Garage door openers are on site	Incomplete
De Young Properties			
Code: ZZ_3205 Category: Builder Personnel Partner: De Young Properties	Location: Type:	Description: Missing gas meter	Incomplete
Donald P. Dick			

All Defects	Lot 123/Tract 0273		
Code: ZZ_3181 Category: HVAC Partner: Donald P. Dick	Location: Type:	Description: Air vent missing in master closet	Incomplete
Elia Painting			
Code: ZZ_3184 Category: Paint Partner: Elia Painting	Location: Type:	Description: Sand and repaint window sill in master bedroom	Incomplete
Code: ZZ_3185 Category: Paint Partner: Elia Painting	Location: Type:	Description: Paint touch up in master bed on opposite side of door	Incomplete
Code: ZZ_3186 Category: Paint Partner: Elia Painting	Location: Type:	Description: Sand and paint baseboard in bed 2	Incomplete
Code: ZZ_3188 Category: Paint Partner: Elia Painting	Location: Type:	Description: Paint drip in bed 2 closet and paint touch up in bullnose	Incomplete
Code: ZZ_3189 Category: Paint Partner: Elia Painting	Location: Type:	Description: Sand and paint railing on upstairs landing	Incomplete
Code: ZZ_3191 Category: Paint Partner: Elia Painting	Location: Type:	Description: Paint blemishes in stairwell	Incomplete
Code: ZZ_3192 Category: Paint Partner: Elia Painting	Location: Type:	Description: Sand and paint stair rail heading up to landing	Incomplete
Code: ZZ_3193 Category: Paint Partner: Elia Painting	Location: Type:	Description: Paint bullnose on pony wall in stairwell	Incomplete

All Defects	Lot 123/Tract 0273		
Code: ZZ_3194 Category: Paint Partner: Elia Painting	Location: Type:	Description: Paint island pony wall	Incomplete
Code: ZZ_3196 Category: Paint Partner: Elia Painting	Location: Type:	Description: Paint and clean up around light switch in pantry	Incomplete
Code: ZZ_3200 Category: Paint Partner: Elia Painting	Location: Type:	Description: Paint powder bath wall	Incomplete
Fenceworks			
Code: ZZ_3204 Category: Fence Partner: Fenceworks	Location: Type:	Description: Missing gate on side yard	Incomplete
Fresno Shower Door & Mirror			
Code: ZZ_3177 Category: Shower Door & Mirror Partner: Fresno Shower Door & Mirror	Location: Type:	Description: Shower enclosure in master bathroom not installed	Incomplete
Ohanians Drywall			
Code: ZZ_3182 Category: Drywall Partner: Ohanians Drywall	Location: Type:	Description: 3 lines in drywall in water closet	Incomplete
Code: ZZ_3183 Category: Drywall Partner: Ohanians Drywall	Location: Type:	Description: Drywall booger in master bedroom	Incomplete

All Defects	Lot 123/Tra	Lot 123/Tract 0273		
Code: ZZ_3187 Category: Drywall Partner: Ohanians Drywall	Location: Type:	Description: Drywall booger in bed 2 closet	Incomplete	
Code: ZZ_3190 Category: Drywall Partner: Ohanians Drywall	Location: Type:	Description: Drywall boogers in several locations in stairwell	Incomplete	
Quality Plumbing				
Code: ZZ_3202 Category: Plumbing Partner: Quality Plumbing	Location: Type:	Description: Please install pedistel sink in powder bathroom	Incomplete	
Code: ZZ_3203 Category: Plumbing Partner: Quality Plumbing	Location: Type:	Description: Please install water heater in garage	Incomplete	
Visalia Tile				
Code: ZZ_3178 Category: Tile Partner: Visalia Tile	Location: Type:	Description: Clean excess grout off tile in master shower	Incomplete	
Code: ZZ_3198 Category: Tile Partner: Visalia Tile	Location: Type:	Description: Replace several tiles on kitchen backsplash have chips in them	Incomplete	
Westech				
Code: ZZ_3179 Category: Electrical Partner: Westech	Location: Type:	Description: Missing vanity lights in master bathroom	Incomplete	
Code: ZZ_3201 Category: Electrical Partner: Westech	Location: Type:	Description: Install vanity light in powder bath	Incomplete	