





Lot 29/Tract 6100		Items: 49	CH Items: 1	Checklist Inspections: 0
<div>Cabinet Connection</div>				
Code: ZZ_427	Location: Bathroom 1	Type: Issues with cabinet drawers and/or doors functionality	Description: Left drawers on left vanity are out of alignment	Incomplete
Category: Cabinets				
Partner: Cabinet Connection				
Code: ZZ_428	Location: Bathroom 1	Type: Issues with cabinet drawers and/or doors functionality	Description: Right drawers on left vanity are out of alignment	Incomplete
Category: Cabinets				
Partner: Cabinet Connection				
Code: ZZ_429	Location: Bathroom 1	Type: Issues with cabinet drawers and/or doors functionality	Description: Right drawers on right vanity are out of alignment	Incomplete
Category: Cabinets				
Partner: Cabinet Connection				
Code: ZZ_430	Location: Bathroom 1	Type: Issues with cabinet drawers and/or doors functionality	Description: Scratched door on left vanity	Incomplete
Category: Cabinets				
Partner: Cabinet Connection				
Code: ZZ_431	Location: Bathroom 1	Type: Issues with cabinet drawers and/or doors functionality	Description: Lefts drawers on right vanity out of alignment	Incomplete
Category: Cabinets				
Partner: Cabinet Connection				
Code: ZZ_432	Location: Bathroom 1	Type: Issues with cabinet drawers and/or doors functionality	Description: Center blank is out of alignment	Incomplete
Category: Cabinets				
Partner: Cabinet Connection				
Code: ZZ_433	Location: Bathroom 1	Type: Issues with cabinet drawers and/or doors functionality	Description: Nail holes showing on center vanity	Incomplete
Category: Cabinets				
Partner: Cabinet Connection				

Lot 29/Tract 6100		Items: 49	CH Items: 1	Checklist Inspections: 0
Code: ZZ_434				
Category: Cabinets	Location: Bathroom 1		Description: Missing tee on both vanities	Incomplete
Partner: Cabinet Connection	Type: Issues with cabinet drawers and/or doors functionality			
Code: ZZ_448				
Category: Cabinets	Location: Bathroom 2		Description: Align doors and drawers on left side of vanity	Incomplete
Partner: Cabinet Connection	Type: Issues with cabinet drawers and/or doors functionality			
Code: ZZ_449				
Category: Cabinets	Location: Bathroom 2		Description: Align doors and drawers on right side of vanity	Incomplete
Partner: Cabinet Connection	Type: Issues with cabinet drawers and/or doors functionality			
Code: ZZ_450				
Category: Cabinets	Location: Bathroom 2		Description: Tee missing	Incomplete
Partner: Cabinet Connection	Type: Issues with cabinet drawers and/or doors functionality			
Code: ZZ_466				
Category: Cabinets	Location: Kitchen		Description: Scratches I. Oven surround	Incomplete
Partner: Cabinet Connection	Type: Cabinet drawers and/or doors need to be adjusted			
Code: ZZ_467				
Category: Cabinets	Location: Kitchen		Description: Scratches on drawer under oven	Incomplete
Partner: Cabinet Connection	Type: Cabinet drawers and/or doors need to be adjusted			
Code: ZZ_468				
Category: Cabinets	Location: Kitchen		Description: Twe missing	Incomplete
Partner: Cabinet Connection	Type: Cabinet drawers and/or doors need to be adjusted			
Code: ZZ_469				
Category: Cabinets	Location: Kitchen		Description: Adjust drawers right of oven are out of alignment	Incomplete
Partner: Cabinet Connection	Type: Cabinet drawers and/or doors need to be adjusted			

Lot 29/Tract 6100		Items: 49	CH Items: 1	Checklist Inspections: 0
Code: ZZ_470				
Category: Cabinets	Location: Kitchen		Description: Adjust drawers and doors out of alignment on bottom cabinets left of oven	Incomplete
Partner: Cabinet Connection	Type: Cabinet drawers and/or doors need to be adjusted			
Code: ZZ_471				
Category: Cabinets	Location: Kitchen		Description: Adjust cabinets by fridge surround	Incomplete
Partner: Cabinet Connection	Type: Cabinet drawers and/or doors need to be adjusted			
Code: ZZ_472				
Category: Cabinets	Location: Kitchen		Description: Scratches by fridge surround	Incomplete
Partner: Cabinet Connection	Type: Cabinet drawers and/or doors need to be adjusted			
 Elia Painting				
Code: ZZ_438				
Category: Paint	Location: Bathroom 1		Description: Touch up door casing to water closet	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: ZZ_442				
Category: Paint	Location: Bedroom 1		Description: Touch up paint on window sill	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: ZZ_443				
Category: Paint	Location: Bedroom 2		Description: Touch up door casing to closet	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: ZZ_444				
Category: Paint	Location: Bedroom 2		Description: Remove numbers off hindges	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: ZZ_445				
Category: Paint	Location: Bedroom 3		Description: Remove numbers off hindges	Incomplete
Partner: Elia Painting	Type: Touch-up required			

Lot 29/Tract 6100		Items: 49	CH Items: 1	Checklist Inspections: 0
Code: ZZ_446				
Category: Paint	Location: Bedroom 4		Description: Paint touch up by light switch's	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: ZZ_447				
Category: Paint	Location: Bedroom 4		Description: Paint touch up by outlet by window	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: ZZ_453				
Category: Paint	Location: Bathroom 2		Description: Paint touch up on door casing	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: ZZ_458				
Category: Paint	Location: Bathroom 3		Description: Paint after drywall repair	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: ZZ_459				
Category: Paint	Location: Bathroom 3		Description: Paint door casing	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: ZZ_463				
Category: Paint	Location: Great Room		Description: Touch up drywall repair	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: ZZ_464				
Category: Paint	Location: Dining Nook		Description: Touch up to the left of window	Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: ZZ_465				
Category: Paint	Location: Dining Nook		Description: Re caulk by baseboard tight of window	Incomplete
Partner: Elia Painting	Type: Touch-up required			
	Fresno Shower Door & Mirror			

Lot 29/Tract 6100		Items: 49	CH Items: 1	Checklist Inspections: 0
Code: ZZ_435				
Category: Shower Door & Mirror	Location: Bathroom 1	Type: Installation issue or defect	Description: Missing mirrors	Incomplete
Partner: Fresno Shower Door & Mirror				
Code: ZZ_436				
Category: Shower Door & Mirror	Location: Bathroom 1	Type: Installation issue or defect	Description: Missing shower glass	Incomplete
Partner: Fresno Shower Door & Mirror				
Code: ZZ_451				
Category: Shower Door & Mirror	Location: Bathroom 2	Type: Installation issue or defect	Description: Missing mirror	Incomplete
Partner: Fresno Shower Door & Mirror				
Code: ZZ_460				
Category: Shower Door & Mirror	Location: Bathroom 3	Type: Installation issue or defect	Description: Missing mirror	Incomplete
Partner: Fresno Shower Door & Mirror				
<div><div></div> Ideal Custom Tile</div>				
Code: ZZ_437				
Category: Tile	Location: Bathroom 1	Type: Grout at tile is cracked, missing, wrong color, and/or needs touch-up	Description: Missing grout on tile toe kick	Incomplete
Partner: Ideal Custom Tile				
Code: ZZ_452				
Category: Tile	Location: Bathroom 2	Type: Grout at tile is cracked, missing, wrong color, and/or needs touch-up	Description: Missing grout by door casing	Incomplete
Partner: Ideal Custom Tile				
Code: ZZ_454				
Category: Tile	Location: Hallway	Type: Crack or chipped tile	Description: Chipped tile in hall by bath 2	Incomplete
Partner: Ideal Custom Tile				

Lot 29/Tract 6100		Items: 49	CH Items: 1	Checklist Inspections: 0
Code: ZZ_455				
Category: Tile	Location: Hallway		Description: Missing grout by bed 2	Incomplete
Partner: Ideal Custom Tile	Type: Crack or chipped tile			
Code: ZZ_461				
Category: Tile	Location: Great Room		Description: Missing grout by large window by back tard	Incomplete
Partner: Ideal Custom Tile	Type: Grout at tile is cracked, missing, wrong color, and/or needs touch-up			
Code: ZZ_473				
Category: Tile	Location: Kitchen		Description: Grout cracked by island	Incomplete
Partner: Ideal Custom Tile	Type: Grout at tile is cracked, missing, wrong color, and/or needs touch-up			
Code: ZZ_474				
Category: Tile	Location: Kitchen		Description: Grout cracked on tile backsplash	Incomplete
Partner: Ideal Custom Tile	Type: Grout at tile is cracked, missing, wrong color, and/or needs touch-up			
 Ohanians Drywall				
Code: ZZ_457				
Category: Drywall	Location: Bathroom 3		Description: Repair holes where wire was being searched for	Incomplete
Partner: Ohanians Drywall	Type: Drywall has crack, gash, hole, and/or gouge			
Code: ZZ_462				
Category: Drywall	Location: Great Room		Description: Drywall touch up by happ	Incomplete
Partner: Ohanians Drywall	Type: Drywall texture issues			
 Quality Plumbing				
Code: ZZ_439				
Category: Plumbing	Location: Bathroom 1		Description: No hot water. Changed mode and will test again at the end	CRITICAL Incomplete
Partner: Quality Plumbing	Type: Hot water not working			

Lot 29/Tract 6100		Items: 49	CH Items: 1	Checklist Inspections: 0
Code: ZZ_440				
Category: Plumbing	Location: Bathroom 1	Type: Hot water not working	Description: Toilets won't flush fire sprinklers are not hooked up	CRITICAL Incomplete
Partner: Quality Plumbing				
<div><div></div>Spence Fence</div>				
Code: ZZ_475				
Category: Fence	Location: Backyard	Type: Fence Boards or Posts cracked/warped/defective	Description: Gate won't latch	Incomplete
Partner: Spence Fence				
<div><div></div>Westech</div>				
Code: ZZ_441				
Category: Electrical	Location: Bedroom 1	Type: Light fixture, or pieces of light fixture, are missing	Description: Missing light	Incomplete
Partner: Westech				
Code: ZZ_456				
Category: Electrical	Location: Bathroom 3	Type: Light fixtures, or pieces of light fixtures, are missing	Description: Missing vanity light in powder bath	Incomplete
Partner: Westech				