

Lot 591/Tract 0273	Items: 20	CH Items: 0	Checklist Inspections: 210
--------------------	-----------	-------------	----------------------------------

<div></div> Anlin Windows			
Code: ZZ_1762			
Category: Windows	Location: Dining Nook	Description: Scratches on slider	Incomplete
Partner: Anlin Windows	Type: Window glass has scratches		
<div></div> Cabinet Connection			
Code: ZZ_1745			
Category: Cabinets	Location: Kitchen	Description: Drawer left of oven needs adjustment	Incomplete
Partner: Cabinet Connection	Type: Cabinet drawers and/or doors need to be adjusted		
Code: ZZ_1746			
Category: Cabinets	Location: Kitchen	Description: Scratches on drawer faces left of oven	Incomplete
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks		
Code: ZZ_1747			
Category: Cabinets	Location: Kitchen	Description: Handel on left cabinet door damaged	Incomplete
Partner: Cabinet Connection	Type: Cabinet missing trim or other parts		
Code: ZZ_1748			
Category: Cabinets	Location: Kitchen	Description: Cabinet scratches by microwave	Incomplete
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks		
Code: ZZ_1749			
Category: Cabinets	Location: Kitchen	Description: Scratches on Twe right of oven	Incomplete
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks		

Code: ZZ_1750			
Category: Cabinets	Location: Kitchen	Description: Scratches on drawers right of oven	Incomplete
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks		
Code: ZZ_1751			
Category: Cabinets	Location: Kitchen	Description: Scratches on door face right of oven	Incomplete
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks		
Code: ZZ_1752			
Category: Cabinets	Location: Kitchen	Description: Scratches on fridge surround	Incomplete
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks		
Code: ZZ_1753			
Category: Cabinets	Location: Kitchen	Description: Scratches on crown above fridge surround	Incomplete
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks		
Code: ZZ_1754			
Category: Cabinets	Location: Kitchen	Description: Scratches on door faces on island	Incomplete
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks		
Code: ZZ_1755			
Category: Cabinets	Location: Kitchen	Description: Adjust drawers on island	Incomplete
Partner: Cabinet Connection	Type: Cabinet drawers and/or doors need to be adjusted		
Code: ZZ_1760			
Category: Cabinets	Location: Bathroom 2	Description: Blemish and scratches on right door face	Incomplete
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets		

Code: ZZ_1764			
Category: Stone Veneer	Location: Exterior	Description: Nail left on stone	Incomplete
Partner: John Ventresca Co	Type: Stone veneer missing or damaged		
<div><div></div>Ohanians Drywall</div>			
Code: ZZ_1756			
Category: Drywall	Location: Bedroom 2	Description: Hole in drywall by coax	Incomplete
Partner: Ohanians Drywall	Type: Drywall has crack, gash, hole, and/or gouge		
<div><div></div>Premier Door</div>			
Code: ZZ_1757			
Category: Millwork	Location: Bedroom 2	Description: Missing glide for closet door	Incomplete
Partner: Premier Door	Type: Closet needs glide rail		
Code: ZZ_1758			
Category: Millwork	Location: Bedroom 3	Description: Chip in trim for closet door	Incomplete
Partner: Premier Door	Type: Baseboards missing or have chips/gouges		
Code: ZZ_1759			
Category: Millwork	Location: Bedroom 3	Description: Missing glide for closet door	Incomplete
Partner: Premier Door	Type: Missing bypass guide		
<div><div></div>Quality Plumbing</div>			
Code: ZZ_1761			
Category: Plumbing	Location: Bathroom 2	Description: Rust at bottom of tub	Incomplete
Partner: Quality Plumbing	Type: Defect(s) in Bath/Shower fitter/surround		
<div><div></div>Tri Valley Plastering & Drywall</div>			

Code: ZZ_1763

Category: Stucco	Location: Exterior	Description: Fog splotches areas around home	Incomplete
Partner: Tri Valley Plastering & Drywall	Type: Inconsistent Fog coat		