

| | |
|-------------|------------------|
| All Defects | Lot 4/Tract 6164 |
|-------------|------------------|

Elia Painting

| | | | |
|------------------------|--------------------------|---|------------|
| Code: ZZ_1329 | Location: Garage | Description: Gash in door casing door from garage to laundry room | Incomplete |
| Category: Paint | Type: Chip/gouge/scratch | | |
| Partner: Elia Painting | | | |