## **De Young Properties**

Lot 360/Tract 0273	Items: 17	CH Items: 2	Checklist Inspections: 0	
Cabinet Connection				
Code: ZZ_1281 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen  Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on inside of fridge surround	Complete	
Code: ZZ_1282 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen  Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on cabinet doors right of fridge surround	Complete	
Code: ZZ_1283 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen  Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on drawers right of fridge surround	Complete	
Code: ZZ_1284 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen  Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on drawers on island	Complete	
Code: ZZ_1285 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen  Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on drawer faces right side of oven	Complete	
Code: ZZ_1286 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen  Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on door faces rights side of microwave	Complete	

Lot 360/Tract 0273	Items: 17	CH Items: 2	Checklist Inspections: 0
Code: ZZ_1287  Category: Cabinets  Partner: Cabinet Connection	Location: Kitchen  Type: Cabinet missing trim or other parts	Description: Missing Twe in kitchen	Complete
Code: ZZ_1290 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 2  Type: Cabinet missing trim or other parts	Description: Missing Twe in bath 2	Complete
Code: ZZ_1291 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1  Type: Cabinet missing trim or other parts	Description: Missing Twe in master bath	Complete
Code: ZZ_1292 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1  Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on center drawers	Complete
Code: ZZ_1293 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1  Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on left of doors	Complete
Elia Painting			
Code: ZZ_1296 Category: Paint Partner: Elia Painting	Location: Bedroom 2  Type: Touch-up required	Description: Touch up left of window	Complete
Ferguson			
Code: ZZ_1288  Category: Appliances  Partner: Ferguson	Location: Kitchen  Type: Appliance(s) missing	Description: Missing appliances	CRITICAL Complete

Description: Big hole

under address box

Complete

Category: Stucco

Partner: Tri Valley

Plastering & Drywall

Location: Exterior

Type: Chip/crack/gouge