

All Defects		Lot 1/Tract 6164		
<div><div></div><div>Cabinet Connection</div></div>				
Code: ZZ_2577				
Category: Cabinets	Location:	Description: Cabinet drawer missing handle in kitchen		Incomplete
Partner: Cabinet Connection	Type:			
Code: ZZ_2578				
Category: Cabinets	Location:	Description: Un even stain around microwave and oven trim		Incomplete
Partner: Cabinet Connection	Type:			
Code: ZZ_2579				
Category: Cabinets	Location:	Description: Cabinet scratches on corners of drawers in kitchen		Incomplete
Partner: Cabinet Connection	Type:			
Code: ZZ_2580				
Category: Cabinets	Location:	Description: Adjust doors in kitchen		Incomplete
Partner: Cabinet Connection	Type:			
Code: ZZ_2584				
Category: Cabinets	Location:	Description: Cabinet scratches in master bathroom		Incomplete
Partner: Cabinet Connection	Type:			
Code: ZZ_2585				
Category: Cabinets	Location:	Description: Adjust drawers in master bathroom		Incomplete
Partner: Cabinet Connection	Type:			
Code: ZZ_2589				
Category: Cabinets	Location:	Description: Grout crack in master bath		Incomplete
Partner: Cabinet Connection	Type:			
Code: ZZ_2594				
Category: Cabinets	Location:	Description: Adjust drawers in bath 2		Incomplete
Partner: Cabinet Connection	Type:			
<div><div></div><div>Elia Painting</div></div>				

Code: ZZ_2581	Location:		
Category: Paint	Type:	Description: Paint touch up in great room	Incomplete
Partner: Elia Painting			
Code: ZZ_2582	Location:		
Category: Paint	Type:	Description: Paint touch up in entry to master bed	Incomplete
Partner: Elia Painting			
Code: ZZ_2583	Location:		
Category: Paint	Type:	Description: Paint touch up in master bedroom	Incomplete
Partner: Elia Painting			
Code: ZZ_2587	Location:		
Category: Paint	Type:	Description: Paint touch up in master closet	Incomplete
Partner: Elia Painting			
Code: ZZ_2588	Location:		
Category: Paint	Type:	Description: Paint attic access	Incomplete
Partner: Elia Painting			
Code: ZZ_2591	Location:		
Category: Paint	Type:	Description: Paint touch up in bed 2	Incomplete
Partner: Elia Painting			
Code: ZZ_2592	Location:		
Category: Paint	Type:	Description: Paint you up bed 4	Incomplete
Partner: Elia Painting			
Code: ZZ_2595	Location:		
Category: Paint	Type:	Description: Paint corner baseboard in great room	Incomplete
Partner: Elia Painting			
Code: ZZ_2596	Location:		
Category: Paint	Type:	Description: Paint touch up in laundry room	Incomplete
Partner: Elia Painting			

Code: ZZ_2598	Location:		
Category: Fence	Type:	Description: Fence not complete	Incomplete
Partner: Fenceworks			
<div><div></div>Ferguson</div>			
Code: ZZ_2597	Location:		
Category: Appliances	Type:	Description: Appliances not installed	Incomplete
Partner: Ferguson			
<div><div></div>Ideal Custom Tile</div>			
Code: ZZ_2590	Location:		
Category: Tile	Type:	Description: Grouting in master shower	Incomplete
Partner: Ideal Custom Tile			
Code: ZZ_2593	Location:		
Category: Tile	Type:	Description: Grout touch up in bath 2	Incomplete
Partner: Ideal Custom Tile			
<div><div></div>Ohanians Drywall</div>			
Code: ZZ_2586	Location:		
Category: Drywall	Type:	Description: Drywall touch up in master bath	Incomplete
Partner: Ohanians Drywall			