

All Defects		Lot 31/Tract 6102	
<div><div></div></div>	Cabinet Connection		
Code: ZZ_096			
Category: Cabinets	Location: Kitchen	Description: Missing cabinet handle in kitchen island	Incomplete
Partner: Cabinet Connection	Type: Part missing		
Code: ZZ_098			
Category: Cabinets	Location: Kitchen	Description: Cabinet door needs to be adjusted in kitchen island - right door	Incomplete
Partner: Cabinet Connection	Type: Adjust door(s)		
Code: ZZ_099			
Category: Cabinets	Location: Kitchen	Description: Please build box around hood vent in kitchen	Incomplete
Partner: Cabinet Connection	Type: Part missing		
Code: ZZ_100			
Category: Cabinets	Location: Kitchen	Description: Cabinet scratches in kitchen - look for blue tape	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)		
Code: ZZ_101			
Category: Cabinets	Location: Kitchen	Description: Cracked inside cabinet Please replace	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)		
Code: ZZ_102			
Category: Cabinets	Location: Kitchen	Description: Check inside cabinets - stains on shelves in cabinets on either side of fridge. Please repair	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)		
Code: ZZ_103			
Category: Cabinets	Location: Kitchen	Description: Scratches inside of cabinet door in corner cabinet	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)		

All Defects		Lot 31/Tract 6102	
Code: ZZ_104			
Category: Cabinets	Location: Kitchen	Description: Island bracket has nails sticking out and has paint spray Please address	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)		
Code: ZZ_105			
Category: Cabinets	Location: Bathroom 1	Description: Missing cabinet pull in master bathroom	Incomplete
Partner: Cabinet Connection	Type: Part missing		
Code: ZZ_107			
Category: Cabinets	Location: Bathroom 1	Description: Cabinet drawer in master vanity needs to be adjusted	Incomplete
Partner: Cabinet Connection	Type: Adjust door(s)		
Code: ZZ_109			
Category: Cabinets	Location: Bathroom 2	Description: Cabinet scratches in bath 2	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)		
 De Young Properties			
Code: ZZ_108			
Category: Tile	Location: Bathroom 1	Description: Scrape grout off of tile under vanity in master bath	Incomplete
Partner: De Young Properties	Type: Grout cracked/missing		
Code: ZZ_110			
Category: Appliances	Location: Laundry Room	Description: Washer and dryer has stains	Incomplete
Partner: De Young Properties	Type: Scratch		
Code: ZZ_112			
Category: Paint	Location: Bedroom 1	Description: Various paint touch io	Incomplete
Partner: De Young Properties	Type:		
 Ferguson			

All Defects		Lot 31/Tract 6102			
Code: ZZ_106		Location: Bathroom 1		Description: Various scratches in master bath cabinets follow blue tape	Incomplete
Category: Cabinets		Type: Dent(s), ding(s), scratch(es)			
Partner: Ferguson					
 Ohanians Drywall					
Code: ZZ_095		Location: Kitchen		Description: Drywall touch up in kitchen above the cabinets - next to fridge	Incomplete
Category: Drywall		Type: Crack/gash/ding			
Partner: Ohanians Drywall					
 Premier Door					
Code: ZZ_111		Location: Bedroom 4		Description: Closet doors in bedroom 4	Incomplete
Category: Millwork		Type:			
Partner: Premier Door					
 Tile Interiors					
Code: ZZ_097		Location: Kitchen		Description: Grout crack in kitchen next to oven	Incomplete
Category: Tile		Type: Grout cracked/missing			
Partner: Tile Interiors					